



Warranty Claim Form

Date: 9/24/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3725N9918847
Reflection 337RLS
Retail Purchase Date: 2/4/2022
Work Started: 8/27/2024
Work Completed: 8/27/2024

Claim Status: Paid
Dealer Work Order #: 10896
Unit Offline Date: 1/19/2022

Claim #: 836151
Labor: \$0.00
Parts: \$0.00
Shipping: \$0.00
Total: \$120.58

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

Thomas Valnoha
2159 Wisconsin St
Friendship, Wisconsin 53934-9311
United States
847-507-0789

Operation Line # 1

Flat Rate Code: 170036 Slide Out Assembly - Bell Stop R&R *Fault Code:* Improper Installation/Build

Problem: PA 796185* SSlide for dining/kitchen room, cans are starting to crumple. Will like tech to come check out the unit when dropping Monday for further explanation.

Hours: 0

Cause: The holes in the frame are too big, and it caused both bell stops to pull through the holes.

Amount: 0.00

Remedy: PA 796185 was approved already- this is for the sublet for the certified welder to close up both the holes.

Sublet Repairs:
\$120.58

Manufacturer #:

Model #:

Serial #: