

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 10928B

|                 |                      |                 |                   |
|-----------------|----------------------|-----------------|-------------------|
| Date In:        | 12 AUG 24            | Author:         | MGRAY             |
| Promised Date:  | 14 AUG 24            | Stock No:       | 11102             |
| :               | :                    | Year:           | 2024              |
| Customer Name:  | 13521 - WEGER, DARYL | Manufacturer:   | FOREST RIVER      |
| Address:        | 3954 E ARBOR LAKES   | Brand:          | PUMA DESTINATION  |
| :               | HERNANDO, FL         | Model:          | 39FKL             |
| Postal/Zip:     | 34442                | Miles/Hrs:      | 0                 |
| Phone#(res):    | 608-579-1176         | Exterior Color: | :                 |
| Phone#(bus):    | :                    | Unit Type:      | TT-TRAVEL TRAILER |
| Cell Phone:     | :                    | License#:       | :                 |
| Email:          | DMWEGS@YAHOO.COM     | Tag#:           | DEL@ST            |
| Purchased Date: | 01 AUG 24            | :               | :                 |
| Delivery Date:  | 14 AUG 24            | :               | :                 |
| InService Date: | :                    | :               | :                 |
| Serial#:        | 4X4TPUR20RP101400    | :               | :                 |

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 2 - VENT RIGHT NEXT TO      W    1021    FORES
          THE BED (RIGHTSIDE) BULDGES OFF OF THE
          WALL. NEEDS EXTRA SCREWS OR TO BE
          ADJUSTED.
          CAUSE:      Mfg improper install, not secured
                      correctly. WILL NEED .20 FOR REPAIRS.
          CORRECTION: Added 2 screws it now lays flat
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 01 ods sofa the      W    1021    FORES
          back has a hole in it
          CAUSE:      Sofa back has a small rip in it Order
                      new back of sofa .tag for sofa is in
                      pictures. 55wide x 22 tall .WILL NEED
                      .30 FOR REMOVAL AND REPLACEMENT OF SOFA
          CORRECTION: WILL NEED A NEW SOFA.
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 02 ds sofa seat      W    1021    FORES
          has a stain
          CAUSE:      Silicone on the sofa cushions WILL NEED
                      .30 FOR TIME SPENT CLEANING STAIN.
          CORRECTION: Cleaned off with quick solve Pics taken
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 03. Positive         W    1021    FORES
          battery cable the end is missing
          CAUSE:      Mfg did not correctly install the end it
                      broke off. WILL NEED .50 FOR REPAIR.
          CORRECTION: Cut positive wire then crimped new end
                      onto positive line and pulled to be sure
                      it was crimped tightly it is then used
                      electrical tape to secure more
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 06 Dining area      W    1021    FORES
```

Continued on page 2

Work Order : 10928B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
          floor covering has a stain
CAUSE:   Stained floor covering from mfg. WILL
          NEED .30 FOR STAIN REMOVAL.
CORRECTION: Used quick solve to remove stains   Pics
          taken
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 07 Water pump is   W    1021   FORES
          weak and hardly no pressure coming out
          of. Interior shower head with the pump ,
          other faucets are acceptable pressure
          but pump turns on and off many times
          when any faucet is on
CAUSE:   Low water pressure in int shower when
          using water pump. WILL NEED .40 FOR
          REPAIRS COMPLETED.
CORRECTION: I adjusted water pump for more pressure
          , removed shower faucet to check if
          debris in lines doing both of these did
          absolutely nothing . changed shower hose
          the hole in hose for water to travel is
          a bit bigger still low pressure so I
          recommend use city water when showering
          you have good pressure then there are no
          leaks in line so I'm thinking the length
          water has to travel to shower line is a
          far distance  and the water pump
          installed cannot give enough pressure to
          make water flow with pressure the way
          it's built
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 08 Protruding      W    1021   FORES
          nails throughout the unit
CAUSE:   Protruding nails that were never set.
          WILL NEED .30 TO SET ALL PROTRUDING
          NAILS.
CORRECTION: Used nail set to set the nails
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 09. Ods sliderooms W    1021   FORES
          top fascia board and the trim for
          ceiling of slideroom good sized gap
          between them
CAUSE:   Gap in trim WILL NEED .20 FOR REPAIR.
CORRECTION: Used white silicone to fill cracks in
          slide out ceiling
ISR1    COMPLAINT:  INTERNAL STOCK REPAIR 10. Top and bottom W    1021   FORES
          drawers in the bedrooms dresser do not
          latch all of the way and they do not lay
          flat against face of cabinetry
CAUSE:   Mfg improper install. WILL NEED 1.5 TO
          REMOVE, ADJUST AND REINSTALL ALL DRESSER
          DRAWERS.
CORRECTION: Removed all drawers adjusted the frame

```

Continued on page 3

Work Order : 10928B

and glides then adjusted rails on side  
of drawers they now open and completely  
close as they should

```
*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
ISR07 019079642578 HH SHW HOSE BK, 59, VINY W-1021      1        9.30        9.30
ISR09 146877        NOVAFLEX SEALANT WHITE W-1021      1       10.14       10.14
*****
```

```
*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50     115.00     57.50
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00     115.00        0.00
ISR01 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.49     115.00     56.35
ISR01 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.00     115.00        0.00
ISR01 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.01     115.00        1.15
ISR02 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.50     115.00     57.50
ISR02 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.00     115.00        0.00
ISR03 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.50     115.00     57.50
ISR03 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.00     115.00        0.00
ISR06 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.50     115.00     57.50
ISR06 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.00     115.00        0.00
ISR07 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.31     115.00     35.65
ISR07 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.00     115.00        0.00
ISR07 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.08     115.00        9.20
ISR07 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.11     115.00     12.65
ISR08 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.50     115.00     57.50
ISR08 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.00     115.00        0.00
ISR09 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.50     115.00     57.50
ISR09 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.00     115.00        0.00
ISR10 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.27     115.00     31.05
ISR10 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.00     115.00        0.00
ISR10 Z991      MISC LABOUR CODE (INTE HOD W-1021      0.23     115.00     26.45
*****
```

```
*****
Job #  Excode  Description      EXTRAS      bill to      Qty      Price      Total
*****
ISR01  SSE      SHOP SUPPLIES - EXTERNAL W-1021      1.00        0.00        0.00
*****
```

```
*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      19.44      517.50      0.00      0.00      0.00      536.94
*****
Totals      19.44      517.50      0.00      0.00      0.00      536.94
*****
```

&amp;k2S

Continued on page 4

Work Order : 10928B

&k0S