



Warranty Claim Form

Date: 9/12/2024

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573TE2627R3438022

Imagine 22MLE

Retail Purchase Date: 4/13/2024

Work Started: 8/8/2024

Work Completed: 8/8/2024

Claim Status: Paid

Dealer Work Order #: 10953

Unit Offline Date: 1/30/2024

Claim #: 832842

Labor: \$57.50

Parts: \$0.00

Shipping: \$0.00

Total: \$57.50

Notes: JPH 8-20-24

Dealer Information

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170

mail@greenewayrv.com

Approved Labor Rate: \$115.00

Customer Information

KENNETH FALK

4816 NORWAY PINE DRIVE
STEVENS POINT, Wisconsin 54482
United States

715-570-2863

Operation Line # 1

Flat Rate Code: 170025 Lippert Schwintek - Re-Synchronize *Fault Code:* Damaged/Maintenance

Problem: Customer states that the slide out is not going out evenly.

Hours: .5

Cause: Check schwintek system for operation. One slide stop. Will need to resynchronize.

Amount: 57.50

Remedy: Check the wire harness for connection, then resynchronize.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: