



Warranty Claim Form

Date: 10/4/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573TR3824R9925585
Reflection 315RLTS
Retail Purchase Date: null
Work Started: 8/20/2024
Work Completed: 8/20/2024

Claim Status: Paid
Dealer Work Order #: 10957
Unit Offline Date: 12/5/2023

Claim #: 840192
Labor: \$80.50
Parts: \$0.00
Shipping: \$12.44
Total: \$92.94

Notes: JPH 9-16-24

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenewayrv.com
Approved Labor Rate: \$115.00

Customer Information

Operation Line # 1

Flat Rate Code: 910044 Recalls/Field Campaign - Overcurrent Protection *Fault Code:* Recall
24v-522/2024-399 910044

Problem: Recall 24v-522; the wiring that enters the underbelly of the trailer is not protected by required 50-amp overcurrent protection once it enters the RV. This defect can put the use are risk of a thermal event.

Hours: .7

Cause: The positive battery wires going into the underbelly were not protected.

Amount: 80.50

Remedy: Installed a 50amp auto-reset breaker on the frame for the positive battery wires.

Sublet Repairs:
\$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
430207 CIRCUIT PROTECTION WIRE KIT	CIRCUIT PROTECTION WIRE KIT		1	1	0.00