

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10962

Date In: 09 AUG 24 Author: AFREEMAN
Promised Date: 25 DEC 24 Stock No: 11043
: Year: 2024
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: FLAGSTAFF MICRO-LITE
: WISCONSIN RAPIDS, WI Model: 21DS
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: WARR APP - 9/7
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 4X4TFLW27RD458074 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: RECALL 51-1798 The Magic Chef W 1021 FORES
refrigerator may not have the proper
vents cut out inside the refrigerator
potentially causing cooling issues.
CAUSE: Safety recall, refer vent holes.
#51-1798
CORRECTION: Follow recall instructions to add two
vent holes in refer model# MCD CR10DSG
Instructions are clear, and we
completed in relative time per
instructions. Tested OK per
specifications.
WARR COMPLAINT: WARRANTY REPAIR 2 - moisture damage, W 1021 FORES
leaking near hoodvent
CAUSE: Solar mount for electrical connections
on roof cracked and seperated allowing
water into roof cavity. Go Power or
similar PV connector needs to be
replaced and resealed. (1hr) Also
cabinetry under microwave needs
repair/replacement from moisture damage.
Need wide seam tape of matching color to
repair cabinetry. WILL NEED 4 HR FOR
REPAIRS.
CORRECTION: 1: Remove PV connector on roof,
carefully remove alpha sealant as close
to membrane as possible, clean surface,
make new connector ends, prep and attach

Continued on page 2

Work Order : 10962

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
new mount, seal with dicore.  2: Removed
hood vent, removed microwave, found a
bunch more rotting wood mold and water
damage, removed pieces of cabinet that
needed replacement, cut new pieces of
wood to replace existing pieces, piece
under microwave was bull nose shaped,
shaped new piece with belt sander,
wrapped new wood to match, installed new
pieces, siliconed where necessary with
matching sandstone nova flex silicone,
reinstalled vent hood and microwave,
cleaned up mess, quick-solv cleaned the
stained countertop. Refreshed and back
to good.

WARR    COMPLAINT:  WARRANTY REPAIR 3 - bathroom door not   W    1021   FORES
closing/latching

CAUSE:   Door latch/catch mounted too deep in
doorframe. Have to slam very hard to get
door to latch. WILL NEED .60 FOR
REPAIRS.

CORRECTION: Cut two notches 1/16" deep in catch,
bent slightly. Brought depth out
slightly, just enough for door to catch
properly now.
    
```

```

*****
Job # Part No      Description           PARTS   Bill to   Qty   Price   Total
*****
WARR0 839085002285  CABLE ENTRY PLATE FOR MC W-1021      1    20.79    20.79
WARR0 149105        NOVAFLEX SEALANT SANDSTO W-1021      1     8.89     8.89
    
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR RW W-1021 0.09 115.00 10.35
ARR01 Z992 MISC LABOUR CODE (WARR RW W-1021 0.41 115.00 47.15
ARR02 Z992 MISC LABOUR CODE (WARR RW W-1021 1.10 115.00 126.50
ARR02 Z992 MISC LABOUR CODE (WARR RW W-1021 0.08 115.00 9.20
ARR03 Z992 MISC LABOUR CODE (WARR RW W-1021 0.60 115.00 69.00
ARR02 Z992 MISC LABOUR CODE (WARR RW W-1021 0.08 115.00 9.20
ARR02 Z992 MISC LABOUR CODE (WARR RW W-1021 0.65 115.00 74.75
ARR02 Z992 MISC LABOUR CODE (WARR RW W-1021 0.12 115.00 13.80
ARR02 Z992 MISC LABOUR CODE (WARR RW W-1021 0.18 115.00 20.70
ARR02 Z992 MISC LABOUR CODE (WARR RW W-1021 1.23 115.00 141.45
ARR02 Z992 MISC LABOUR CODE (WARR RW W-1021 0.56 115.00 64.40
    
```

Continued on page 3

Work Order : 10962

```
*****
Job #  Excode   Description  EXTRAS      bill to    Qty   Price   Total
*****
ARR02  SSE       SHOP SUPPLIES - EXTERNAL  W-1021    1.00   0.00    0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1021          29.68    586.50    0.00     0.00    0.00    616.18
      Totals          29.68    586.50    0.00     0.00    0.00    616.18
*****
```

&k2S
&k0S