

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 10979

|                 |                        |                 |                   |
|-----------------|------------------------|-----------------|-------------------|
| Date In:        | 13 AUG 24              | Author:         | MGRAY             |
| Promised Date:  | 31 DEC 24              | Stock No:       | 11032             |
| :               | :                      | Year:           | 2024              |
| Customer Name:  | 15054 - CAVANNA, DENNI | Manufacturer:   | GRAND DESIGN      |
| Address:        | 3931 TIMBER VALLEY DR  | Brand:          | REFLECTION FW     |
| :               | WISCONSIN RAPIDS, WI   | Model:          | 337RLS            |
| Postal/Zip:     | 54494                  | Miles/Hrs:      | :                 |
| Phone#(res):    | 715-869-7852           | Exterior Color: | :                 |
| Phone#(bus):    | 715-869-7852           | Unit Type:      | FW-FIFTH WHEEL    |
| Cell Phone:     | :                      | License#:       | :                 |
| Email:          | gramps6551@gmail.com   | Tag#:           | hard promise 8/16 |
| Purchased Date: | 09 APR 24              | :               | :                 |
| Delivery Date:  | 18 APR 24              | :               | :                 |
| InService Date: | :                      | :               | :                 |
| Serial#:        | 573FR372XR9925850      | :               | :                 |

\*\*\*\*\*

| Job # | Description | JOB INFORMATION                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | Type | Bill To    |
|-------|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------------|
| WARR  | COMPLAINT:  | we replaced bearing buddy on his unit a few weeks ago and now its missing again and cmr is concerned about there being metal shavings in the BEARING FROM THIS. CHECK OUT FOR REPAIRS.                                                                                                                                                                                                                                                                                                                                                                                                          | W    | 1020 GRAND |
|       | CAUSE:      | Bearing buddy dislodged for a second time in same brake drum. WILL NEED 2 HRS FOR ALL REPAIRS.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |      |            |
|       | CORRECTION: | Removed brake drum, outer bearing, and washed out outer bearing. Repacked baring with fresh grease. Jesse recommended wrapping a layer of aluminum tape on a new bearing buddy. I recommend using steel ones instead of the factory aluminum ones that keep dislodging. Gave Jesse's fix a try with aluminum foil tape. Seemed to fit alot more snugly. Again, if problem persist I recommend replacing all with steel bearing buddies. Torqued lugs to factory specifications removed from jack stand. Back to good. Inspected the remaining wheel hubs for loose bearing buddies, looking ok. |      |            |

Continued on page 2

Work Order : 10979

```
*****
Job#  Lab Code  Description   LABOUR   Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR RW   W-1020    0.50   115.00   57.50
*****
```

```
*****
                        BILLINGS SUMMARY
Type Bill Id          Parts    Labour    Sublet    Extras      Tax      Total
*****
W      1020            0.00      57.50      0.00      0.00      0.00      57.50

      Totals            0.00      57.50      0.00      0.00      0.00      57.50
*****
```

&k2S  
&k0S