

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10986

Date In: 14 AUG 24 Author: MGRAY
Promised Date: 27 AUG 24 Stock No: 11081
: Year: 2022
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE Brand: PUMA TT
: CHICAGO, IL Model: 25RKQB
Postal/Zip: 60673-1218 Miles/Hrs:
Phone#(res): 219-534-3167 Exterior Color:
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: reaching out to FR abo
Purchased Date: 29 JUN 24 :
Delivery Date: 03 JUL 24 :
InService Date: :
Serial#: 5ZT2PUPB0N4015826 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WHEEL BEARING ON THE ODS FRONT AXLE, W 1021 FORES
WHEEL BEARING IS LOOSE. NEED
REPLACEMENT, OR REPAIR.
CAUSE: CMR states wheel bearing is loose.
CORRECTION: Started with complaint location, front
ODS axle. Jacked up tire to check for
signs of loose bearing. Detected a very
slight loose axle nut. Dismounted tire,
removed bearing buddy, removed
cotterpin, tightened axle nut one
adjustment. Reinstalled cotterpin.
Reinstalled bearing buddy, remounted
wheel, torqued to factory
specifications.
WARR COMPLAINT: WARRANTY REPAIR 2 - DUST CAP IS MISSING W 1021 FORES
ON DS REAR AXLE.
CAUSE: Missing dust cap, on bearing buddy?
CORRECTION: Dust cap is in place, not sure if
someone completed already? CUSTOMER

Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

ARR01 Z992 MISC LABOUR CODE (WARR RW W-1021 0.42 115.00 48.30
ARR02 Z992 MISC LABOUR CODE (WARR RW W-1021 0.50 115.00 57.50
ARR01 Z992 MISC LABOUR CODE (WARR RW W-1021 0.08 115.00 9.20
ARR01 Z992 MISC LABOUR CODE (WARR RW W-1021 0.50 115.00 57.50

Continued on page 2

Work Order : 10986

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	0.00	172.50	0.00	0.00	0.00	172.50
	Totals	0.00	172.50	0.00	0.00	0.00	172.50

&k2S
&k0S