

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11020

Date In:	19 AUG 24	Author:	MZYWICKI
Promised Date:	31 OCT 24	Stock No:	11167
:	:	Year:	2024
Customer Name:	16584 - PETRILLO, VERO	Manufacturer:	FOREST RIVER
Address:	7840 KOLMAR AVENUE	Brand:	PUMA DESTINATION
:	SKOKIE, IL	Model:	402LFT
Postal/Zip:	60076	Miles/Hrs:	0
Phone#(res):	847-334-7937	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	RASPREIT@GMAIL.COM	Tag#:	10/31
Purchased Date:	28 JUN 24	:	:
Delivery Date:	11 JUL 24	:	:
InService Date:		:	:
Serial#:	4X4TPUS26RP102822	:	:

```
*****
Job #  Description                JOB INFORMATION                Type Bill To
*****
1      COMPLAINT:  CUSTOMER STATES THAT THE BLIND IN THE          W    1021  FORES
          FOOT OF THE LOFT STAIRS- IN BETWEEN THE
          BEDROOM DOOR AND THE SLIDING DOOR- DOES
          NOT GO BACK UP- NEEDS TO BE REPLACED-
CAUSE:    pics taken of shade broken internally
CORRECTION: Will need a new shade ..... REQUEST: .75
          HOURS OF LABOR
2      COMPLAINT:  CUSTOMER STATES THAT THE AWNING DOES NOT W    1021  FORES
          OPERATE CORRECTLY- CUSTOMER STATES THAT
          IT IS NOT RETRACTING PROPERLY- CUSTOMER
          STATES THAT IT IS COMING IN REALLY SLOW
CAUSE:    taken pics for future reference
CORRECTION: the awning is working ok normal
          operation
3      COMPLAINT:  CUSTOMER STATES THAT WHEN IT IS RAINING W    1021  FORES
          REALLY HARD, WATER GETS INTO THE FURNACE
          DOOR CAUSING THE FURNACE TO NOT OPERATE
          DUE TO IT BEING WET- NEEDS TO BE LOOKED
          AT-
CAUSE:    correction water heater door is not
          sealing that well we could use stick on
          rubber seals to seal door for no water
          to get in
CORRECTION: can be done in spring customer closing
          up unit ... REQUEST: 1 HOUR OF LABOR
```

Continued on page 2

Work Order : 11020

```
*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
1      82205364      SHADE ROLLER 27X72 BAMBO W-1021      0      54.59      0.00
3      711217014918 D SEAL W/TAPE BLACK .5X3 W-1021      0      0.68      0.00
*****
```

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to      Hrs      Rate      Total
*****
3 WARR      MANUFACTURER WARRANTY JS W-1021      0.50      115.00      57.50
2 WARR      MANUFACTURER WARRANTY JS W-1021      0.50      115.00      57.50
1 WARR      MANUFACTURER WARRANTY JS W-1021      0.50      115.00      57.50
1 WARR      MANUFACTURER WARRANTY      W-1021      0.00      115.00      0.00
3 WARR      MANUFACTURER WARRANTY      W-1021      0.00      115.00      0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      0.00      172.50      0.00      0.00      0.00      172.50

Totals      0.00      172.50      0.00      0.00      0.00      172.50
*****
```

&k2S
&k0S