

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11031

Date In:	21 AUG 24	Author:	KOTT
Promised Date:	25 DEC 24	Stock No:	11102
:	:	Year:	2024
Customer Name:	13521 - WEGER, DARYL	Manufacturer:	FOREST RIVER
Address:	3954 E ARBOR LAKES	Brand:	PUMA DESTINATION
:	HERNANDO, FL	Model:	39FKL
Postal/Zip:	34442	Miles/Hrs:	0
Phone#(res):	608-579-1176	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	DMWEGS@YAHOO.COM	Tag#:	:
Purchased Date:	01 AUG 24	:	:
Delivery Date:	14 AUG 24	:	:
InService Date:	:	:	:
Serial#:	4X4TPUR20RP101400	:	:

```
*****
Job #  Description                JOB INFORMATION                Type Bill To
*****
1      COMPLAINT:  SERVICE CALL TO CUSTOMERS UNIT:  BLUE      I      SEP      POLIC
          LAKE CAMPGROUND 3531 COUNTY RD G
          WISCONSIN DELLS WI 53965
          CORRECTION: COMPLETE
2      COMPLAINT:  CUSTOMER STATES THAT THE ICE MAKER DOES  W      1021    FORES
          NOT OPERATE CORRECTLY- CUSTOMER STATES
          THAT IT WILL GO THROUGH THE CYCLE AND
          ACT LIKE IT IS MAKING USE, BUT DOES NOT
          PRODUCE ANY. ALMOST LIKE WATER IS NOT
          HOOKED UP.
          CAUSE:    water line was shut off behind
                   refrigerator WILL NEED .80 FOR REPAIRS
          CORRECTION: water line was shut off to refrigerator
                   the icemaker is now working
3      COMPLAINT:  CUSTOMER STATES THAT THE ENTRY DOOR DOES W      1021    FORES
          NOT CLOSE/LATCH PROPERLY- CUSTOMER
          STATES THAT THE LATCH DOES NOT CATCH AND
          HE HAS TO PULL REALLY HARD AND BEND THE
          FRAME IN ORDER TO DO IT.
          CAUSE:    pics taken What I found when closing the
                   sliding entry door the latch wouldn't
                   catch framework to lock I also took pics
                   of screen needs new one due to screen
                   ripped and framework bent. WILL NEED 1
                   HR FOR ALL REPAIRS.
          CORRECTION: remove the trimwork from the entry patio
                   door framework and added wedges behind
                   framework to straightened and support I
```

Continued on page 2

Work Order : 11031

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
              also did some adjustments to patio door
              to level the door now latches

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
   2  WARR      MANUFACTURER WARRANTY  JS  W-1021    0.50  115.00  57.50
   3  WARR      MANUFACTURER WARRANTY  JS  W-1021    0.50  115.00  57.50

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
   1  SSE      SHOP SUPPLIES - EXTERNAL  I-SEP    1.00    0.00    0.00
   1  SC       SERVICE CALL              I-SEP   48.00    3.75   180.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
I      SEP        0.00    0.00    0.00   180.00  0.00   180.00
W     1021        0.00   115.00    0.00    0.00  0.00   115.00

      Totals      0.00   115.00    0.00   180.00  0.00   295.00

```

&k2S
&k0S