

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11031

Date In:	21 AUG 24	Author:	MZYWICKI
Promised Date:	25 DEC 25	Stock No:	11102
:	:	Year:	2024
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	39FKL
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	01 AUG 24	:	:
Delivery Date:	14 AUG 24	:	:
InService Date:	:	:	:
Serial#:	4X4TPUR20RP101400	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
1	COMPLAINT:	SERVICE CALL TO CUSTOMERS UNIT: BLUE LAKE CAMPGROUND SITE# 18 3531 COUNTY RD G WISCONSIN DELLS WI 53965	I	SEP POLIC
	CORRECTION:	COMPLETE		
2	COMPLAINT:	CUSTOMER STATES THAT THE ICE MAKER DOES NOT OPERATE CORRECTLY- CUSTOMER STATES THAT IT WILL GO THROUGH THE CYCLE AND ACT LIKE IT IS MAKING USE, BUT DOES NOT PRODUCE ANY. ALMOST LIKE WATER IS NOT HOOKED UP.	W	1021 FORES
	CAUSE:	water line was shut off behind refrigerator WILL NEED .80 FOR REPAIRS		
	CORRECTION:	water line was shut off to refrigerator the icemaker is now working		
3	COMPLAINT:	CUSTOMER STATES THAT THE ENTRY DOOR DOES NOT CLOSE/LATCH PROPERLY- CUSTOMER STATES THAT THE LATCH DOES NOT CATCH AND HE HAS TO PULL REALLY HARD AND BEND THE FRAME IN ORDER TO DO IT.	W	1021 FORES
	CAUSE:	pics taken What I found when closing the sliding entry door the latch wouldn't catch framework to lock I also took pics of screen needs new one due to screen ripped and framework bent. WILL NEED 1 HR FOR ALL REPAIRS.		
	CORRECTION:	remove the trimwork from the entry patio door framework and added wedges behind framework to straightened and support I		

Continued on page 2

Work Order : 11031

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                also did some adjustments to patio door
                                to level the door now latches
4      COMPLAINT:  PER JOE- REQUEST A NEW LATCH FOR THE          W      1021    FORES
                                SLIDING PATIO DOOR- REQUEST:  .50 LABOR
                                AND PART
      CAUSE:        replace patio door latch
      CORRECTION:   remove and install the new patio sliding
                                door latch assembly with key
5      COMPLAINT:  THE PATIO DOOR NEEDS A NEW SLIDING          W      1021    FORES
                                SCREEN DOOR-
      CAUSE:        PER WARRANTY
      CORRECTION:   INSTALLED NEW SCREEN DOOR AND MADE
                                ADJUSTMENTS

```

```

*****
Job # Part No   Description                PARTS                Bill to   Qty    Price    Total
*****
5      20X53515A SCREEN DOOR FOR PATIO DOOR, W-1021          1      53.13    53.13
4      82205269  LOCK PATIO DOOR , BLACK, #2 W-1021          1      63.86    63.86

```

```

*****
Job# Lab Code Description                LABOUR    Mech Bill to   Hrs    Rate    Total
*****
2 WARR      MANUFACTURER WARRANTY JS    W-1021    0.50    115.00    57.50
3 WARR      MANUFACTURER WARRANTY JS    W-1021    0.50    115.00    57.50
4 Z992      MISC LABOUR CODE (WARR JS    W-1021    0.50    140.00    70.00
5 WARR      MANUFACTURER WARRANTY JS    W-1021    0.50    140.00    70.00

```

```

*****
Job # Excode   Description                EXTRAS                bill to   Qty    Price    Total
*****
1 SSE        SHOP SUPPLIES - EXTERNAL I-SEP    1.00    0.00    0.00
1 SC         SERVICE CALL I-SEP    48.00    3.75    180.00
5 FRT        FREIGHT W-1021    1.00    196.20    196.20
4 FRT        FREIGHT FOR JOB 4 PATIO DO W-1021    1.00    18.51    18.51

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id   Parts    Labour    Sublet    Extras    Tax    Total
*****
I   SEP        0.00     0.00     0.00    180.00    0.00    180.00
W   1021       116.99   255.00    0.00    214.71    0.00    586.70

      Totals    116.99   255.00    0.00    394.71    0.00    766.70

```

&k2S
&k0S