



Warranty Claim Form

Date: 1/9/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TR3425R3348199

Reflection 297RSTS

Retail Purchase Date: 8/3/2024

Work Started: 11/18/2024

Work Completed: 11/18/2024

Claim Status: Paid

Dealer Work Order #: 11066

Unit Offline Date: 10/3/2023

Claim #: 862879

Labor: \$46.00

Parts: \$2.16

Shipping: \$1.46

Total: \$49.62

Notes: Sg 8/28/24 This unit has open recalls and must be repaired according to Federal Law before customer takes delivery.
910041 - Reflection Receipt 23v-788/2023 910044 - Overcurrent Protection 24v-522/2024-399 910044

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

17689 W 58TH DR
GOLDEN, Colorado 80403
United States
3038477613

Operation Line # 1

Flat Rate Code: 420004 Lights (Exterior) - R&R Tail Light

Fault Code: Damaged/Maintenance

Problem: Both rear brake light rings are broken.

Hours: .4

Cause: Lights are broken.

Amount: 46.00

Remedy: R&R both rear brake lights. 0.2 hour each.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
420064 TAIL LIGHT REFLECT RING FOR STL 78RB RED	TAIL LIGHT REFLECT RING FOR STL 78RB RED		2	1	2.16