

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11066

Date In:	27 AUG 24	Author:	MGRAY
Promised Date:	25 DEC 24	Stock No:	10999
:	:	Year:	2024
Customer Name:	17047 - JENSEN, DIANE	Manufacturer:	GRAND DESIGN
Address:	17689 W 58TH DR	Brand:	REFLECTION TT
:	GOLDEN, CO	Model:	297RSTS
Postal/Zip:	80403	Miles/Hrs:	0
Phone#(res):	303-847-7613	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	DIJENSEGLDN@MSN.COM	Tag#:	:
Purchased Date:	09 SEP 23	:	:
Delivery Date:	03 AUG 24	:	:
InService Date:	:	:	:
Serial#:	573TR3425R3348199	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - BOTH REAR BRAKE          W    1020    GRAND
          LIGHT RINGS ARE BROKEN.
          CAUSE:         LIGHTS BROKEN NEED REPLACE
          CORRECTION:    drop shipped parts to cmr for install.
WARR    COMPLAINT:  WARRANTY REPAIR 2 - RECALL 23-788(2023)      W    1020    GRAND
          OVERCURRENT PROTECTION NEEDS CHECK
          CAUSE:         Recall.  Their are three white outlets
                        in the unit, and they all tested
                        correct. The job took .3 to complete
          CORRECTION:    Done
1       COMPLAINT:    CUSTOMER STATES THAT THE WINDOW ABOVE      W    1020    GRAND
                        THE DINNETTE IS LEAKING- CUSTOMER STATES
                        THAT THE FLOOR UNDER IT WAS ALL WET AND
                        THERE WAS SOME WATER ON THE TABLE-
                        CUSTOMER STATES THAT THERE WAS SOME HAVE
                        RAIN 3 DAYS IN A ROW BUT THE RAIN WAS
                        COMING IN THE DIRECTION OF THE OPPOSITE
                        SIDE OF THE UNIT- NEEDS TO BE DIAGNOSED-
          CAUSE:         NPF. I sprayed it with water, and I
                        don't see any leaks. I blew out the weep
                        holes, and they are clean. The customer
                        stated that it happened after multiple
                        days of a heavy rain so it's possible
                        that it's a very small hole in the
                        sealant that I can't t see so I cleaned
                        and re sealed around the window to be
                        safe.
```

Continued on page 2

Work Order : 11066

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: Done.
2      COMPLAINT:  RECALL 24V-522                W      1020    GRAND
      CAUSE:       Recall. Installed two 50 amp breakers.
      CORRECTION: Done.

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 8220420064    TAIL LIGHT REFLECT RING    W-1020      2        3.20        6.40
2      010054311182 ANGLE BRACKT TYPE 1-50AM W-1020      2        5.73       11.46

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 RV9AI-10  CLEARANCE/TAIL LENS R&      W-1020      0.00    115.00        0.00
ARR01 RV9AI-10  CLEARANCE/TAIL LENS R&      W-1020      0.00    115.00        0.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK  W-1020      0.00    115.00        0.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK  W-1020      0.50    115.00       57.50
   1 WARR      MANUFACTURER WARRANTY      JGK  W-1020      0.50    115.00       57.50
   2 WARR      MANUFACTURER WARRANTY      JGK  W-1020      0.01    115.00        1.15
   2 WARR      MANUFACTURER WARRANTY      JGK  W-1020      0.49    115.00       56.35

```

```

*****
Job #  Excode    Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01  FRT       FREIGHT FOR JOB WARR01      W-1020      1.00        5.00        5.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020        17.86      172.50        0.00        5.00        0.00      195.36

      Totals        17.86      172.50        0.00        5.00        0.00      195.36

```

&k2S
&k0S