

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11078

Date In:	29 AUG 24	Author:	KOTT
Promised Date:	04 JUL 25	Stock No:	10604
:	:	Year:	2023
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	FLAGSTAFF CLASSIC TT
:	WISCONSIN RAPIDS, WI	Model:	832BWS
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4TFLN28P1902563	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
1      COMPLAINT:  THE TONGUE JACK ON THE UNIT IS NOT          W      1021    FORES
        OPERATING CORRECTLY- WILL NOT OPERATE AT
        ALL-
        CAUSE:      Front jack electronics are moisture
        damaged, control pad deteriorated from
        sun exposure. Needs replacement. Lippert
        Smart Jack. Bad jack. I disconnected
        the wiring, took the bolts out, and
        removed the jack. I secured the new
        jack, hooked the 12 volt wire up and put
        wire loomed around it to protect it. I
        broke down the box and put the old jack
        in the warranty cage.
        CORRECTION: ... Done.
2      COMPLAINT:  LIGHT ABOVE DINETE IS BUSTED. ATTACHED    W      1021    FORES
        PIC. KARENA NOTICED.
        CAUSE:      Light above dinette has been rusting and
        corroded. Moisture leaking into roof
        area from broken solar connection at
        rooftop. See pictures.      Looks like
        solar connector was fastened to roof
        over a piece of debris causing an edge
        to crack, over time the damage spread
        allowing in moisture.      Need to remove
        and replace 12v puck light and solar
        connection on roofline, 2x tube's white
        dicor.      (2hrs to remove and replace
        all components, reseal and test)
```

Continued on page 2

Work Order : 11078

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: R&R solar input connector and dining
puck light.
3 COMPLAINT: R&R SOLAR CONNECTOR                W      1021    FORES
CAUSE:      Broken solar mounting plate  Once I
            figured out which interior light was the
            issue, i replaced it and vacuumed up all
            the Styrofoam that fell out of the hole
            for the light.  I disconnected the
            solar panel wires, cut the dicor around
            the mounting plate, pulled the screws,
            disconnected the wires underneath the
            plate, hooked them up to the new
            mounting plate, secured it to the roof,
            sealed around it with dicor and hooked
            the wires back up.  I put all the
            parts in the warranty cage when I was
            done.
CORRECTION: Done.

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
2      82200671      LIGHT INTERIOR 4 1/2 LED W-1021      1      3.24      3.24
3      822020945      SOLAR ROOF TOP ELECTRICA W-1021      1      33.58      33.58
3      677917000333 Dicor 501LSW-1 EPDM Self W-1021      2      9.59      19.18
1      82207397      SMART POWER TONGUE JACK W-1021      1      254.31      254.31

```

```

*****
Job# Lab Code Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
1 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.26      115.00      29.90
2 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.00      115.00      0.00
1 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.24      115.00      27.60
2 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.17      115.00      19.55
2 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.26      115.00      29.90
2 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.07      115.00      8.05
3 RV8AI-2 CEILING LIGHT R&R DC R JGK W-1021      0.26      115.00      29.90
1 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.86      115.00      98.90
3 RV8AI-2 CEILING LIGHT R&R DC R JGK W-1021      0.14      115.00      16.10
1 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      115.00      0.00
1 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.14      115.00      16.10

```

```

*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
1 FRT      FREIGHT FOR TONGUE JACK JO W-1021      1.00      19.11      19.11

```

Continued on page 3

Work Order : 11078

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	310.31	276.00	0.00	19.11	0.00	605.42
	Totals	310.31	276.00	0.00	19.11	0.00	605.42

&k2S
&k0S