



Warranty Claim Form

Date: 11/15/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FM4123SBB02997
Momentum 351MS
Retail Purchase Date: 7/26/2024
Work Started: 9/12/2024
Work Completed: 9/12/2024

Claim Status: Paid
Dealer Work Order #: 11150
Unit Offline Date: 7/15/2024

Claim #: 850791
Labor: \$138.00
Parts: \$0.00
Shipping: \$0.00
Total: \$138.00

Notes: KK 9.13.24. Approved with modifications. NPF lines denied due to no repair being made.

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

Gary Flahive
661 Jackpine Arbor
Nekoosa, Wisconsin 54457
United States
715-325-2655

Operation Line # 1

Flat Rate Code: 350041 Showers - Seal Base & Surround *Fault Code:* Improper Installation/Build

Problem: Leak in the bathroom by the shower.

Hours: .5

Cause: Leak in the shower door track. I poured water into the track and it leaked out in the rear corner.

Amount: 57.50

Remedy: Re-sealed the bottom of the track.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 660002 Cabinet Doors - Repair Door *Fault Code:* Improper Installation/Build

Problem: Cabinet doors with glass, the screws are stripped and not holding. Maybe longer screws-check.

Hours: .5

Cause: Short screws.

Amount: 57.50

Remedy: Removed both of the hinge screws and replaced them with longer screws. Before I put the longer screws in, I covered the threads in construction adhesive.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 3

Flat Rate Code: 560016 Entry Door - Adjust Door (Main)

Fault Code: Damaged/Maintenance

Problem: Garage door and rear door are tight and do not open easily. Wife is struggling with it. Is there an adjustment to make the movement easier?

Hours: .2

Cause: NPF both the rear entry door and garage door operate very easily. I found out later that it's both the entry doors.

Amount: 23.00

Remedy: Lubed both entry doors so they operate as they should

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: