

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11152B

Date In: 26 SEP 24 Author: KOTT
Promised Date: 25 DEC 24 Stock No: 11155
: Year: 2024
Customer Name: 99348 - HERRON, ELAINE Manufacturer: FOREST RIVER
Address: 110 E STROUD STREET Brand: PUMA DESTINATION
: RANDOLPH, WI Model: 402LFT
Postal/Zip: 53956 Miles/Hrs: 0
Phone#(res): 920-210-3540 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: CRIS SUE@HOTMAIL.COM Tag#:
Purchased Date: 09 SEP 24 :
Delivery Date: 02 OCT 24 :
InService Date: :
Serial#: 4X4TPUS24RP102754 :

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Turned stereo on no W    1021  FORES
        sound to any speakers went through
        diagnosing found both wires to one
        exterior speaker are compromised , to
        fix the problem I will need to run 2 new
        wires from stereo to the speaker which
        requires running the wires through
        existing wire loom in slide down beneath
        and across the underside of the unit
        drill a hole through floor to pull wires
        up and attach to back of the one speaker
        I WILL NEED 8 HOURS TO FIX THIS WIRE
        ISSUE also the wire loom I need to go
        into is on complete opposite side of the
        12 1/2 foot slideroom so have to figure
        out a way to run it behind stove refer ,
        if mfg has issue with time ask them to
        send one of their own to fix the issue
WARR    CORRECTION:  REQUEST 8 HOURS OF LABOR
        COMPLAINT:  WARRANTY REPAIR 2 - Loose trim next to W    1021  FORES
        stove
        CAUSE:      Mfg did not cut trim to correct size too
        big
        CORRECTION: I cut away a bit of the trim then
        secured it with pin nails and filled
        holes REQUEST .50 LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 3 - carpet going up W    1021  FORES
        stairs has stains
*****
```

Continued on page 2

Work Order : 11152B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    CAUSE:      Mfg stained carpeting going up to loft
        CORRECTION: CLEANED REQUEST .50 LABOR
        COMPLAINT: WARRANTY REPAIR 4 - loose trim in rear  W   1021  FORES
                   of unit
        CAUSE:      Loose from mfg
        CORRECTION: Used pin nailer to secure. REQUEST .10
                   LABOR
WARR    COMPLAINT: WARRANTY REPAIR 5 - a lot of sticky      W   1021  FORES
                   debri on the floor
        CAUSE:      Mfg walked through unit with sticky
                   debris on feet also looks like it came
                   off of slide room
        CORRECTION: Used quick solve to clean away the debri
                   REQUEST .50 LABOR
WARR    COMPLAINT: WARRANTY REPAIR 6 -upper windows have    W   1021  FORES
                   sticky stuff all over them
        CAUSE:      Silicone smeared all over exterior top
                   windows
        CORRECTION: Used solvent and a razor blade to remove
                   the silicone REQEUST .50 LABOR
*****

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992     MISC LABOUR CODE (WARR HOD W-1021  0.00 115.00  0.00
ARR01 Z992     MISC LABOUR CODE (WARR HOD W-1021  0.12 115.00 13.80
ARR02 Z992     MISC LABOUR CODE (WARR HOD W-1021  0.49 115.00 56.35
ARR02 Z992     MISC LABOUR CODE (WARR HOD W-1021  0.01 115.00  1.15
ARR03 Z992     MISC LABOUR CODE (WARR HOD W-1021  0.48 115.00 55.20
ARR03 Z992     MISC LABOUR CODE (WARR HOD W-1021  0.02 115.00  2.30
ARR04 Z992     MISC LABOUR CODE (WARR HOD W-1021  0.00 115.00  0.00
ARR04 Z992     MISC LABOUR CODE (WARR HOD W-1021  0.00 115.00  0.00
ARR04 Z992     MISC LABOUR CODE (WARR HOD W-1021  0.10 115.00 11.50
ARR05 Z992     MISC LABOUR CODE (WARR HOD W-1021  0.44 115.00 50.60
ARR05 Z992     MISC LABOUR CODE (WARR HOD W-1021  0.06 115.00  6.90
ARR06 Z992     MISC LABOUR CODE (WARR HOD W-1021  0.50 115.00 57.50
*****

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021          0.00      255.30      0.00      0.00      0.00      255.30
      Totals          0.00      255.30      0.00      0.00      0.00      255.30
*****

```

&k2S
&k0S