

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11152B

Date In:	26 SEP 24	Author:	KOTT
Promised Date:	25 DEC 24	Stock No:	11155
:	:	Year:	2024
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	402LFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	09 SEP 24	:	:
Delivery Date:	02 OCT 24	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS24RP102754	:	:

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - Turned stereo on no W 1021 FORES
sound to any speakers went through
diagnosing found both wires to one
exterior speaker are compromised , to
fix the problem I will need to run 2 new
wires from stereo to the speaker which
requires running the wires through
existing wire loom in slide down beneath
and across the underside of the unit
drill a hole through floor to pull wires
up and attach to back of the one speaker
I WILL NEED 8 HOURS TO FIX THIS WIRE
ISSUE also the wire loom I need to go
into is on complete opposite side of the
12 1/2 foot slideroom so have to figure
out a way to run it behind stove refer ,
if mfg has issue with time ask them to
send one of their own to fix the issue
CAUSE: THE WIRE THAT MANUF. RAN THROUGH THE
CEILING WAS FAULTY-
CORRECTION: REMOVED THE SPEAKER ON THE OUTSIDE- THIS
INVOLVED REMOVING THE SILICONE FROM
AROUND IT- THEN HAD TO REMOVE THE WALL
PANEL-IN ORDER TO DO THIS I ALSO HAD TO
REMOVE THE WINDOW RING- HAD TO DRILL A
HOLD IN THE FLOOR BEHIND THE WALL PANEL
DOWN INTO THE UNDERBELLY THEN RUN IT
ACROSS THE UNIT AND HOOK IT UP TO THE

Continued on page 2

Work Order : 11152B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WIREs THAT ARE BEHIND THE STEREO- HAD TO
          CAUSE:    ROUTE THE WIRES TIGHTLY TO AVOID
          CORRECTION: TOUCHING ANYTHING-
          WARRANTY REPAIR 2 - Loose trim next to stove
          Mfg did not cut trim to correct size too big
          I cut away a bit of the trim then secured it with pin nails and filled holes
          REQUEST .50 LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 3 - carpet going up stairs has stains
          CAUSE:    Mfg stained carpeting going up to loft
          CORRECTION: CLEANED REQUEST .50 LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 4 - loose trim in rear of unit
          CAUSE:    Loose from mfg
          CORRECTION: Used pin nailer to secure. REQUEST .10 LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 5 - a lot of sticky debris on the floor
          CAUSE:    Mfg walked through unit with sticky debris on feet also looks like it came off of slide room
          CORRECTION: Used quick solve to clean away the debris
          REQUEST .50 LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 6 -upper windows have sticky stuff all over them
          CAUSE:    Silicone smeared all over exterior top windows
          CORRECTION: Used solvent and a razor blade to remove the silicone
          REQEUST .50 LABOR
*****

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR W-1021 0.00 115.00 0.00
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.12 115.00 13.80
ARR01 WARR MANUFACTURER WARRANTY W-1021 0.00 115.00 0.00
ARR01 WARR MANUFACTURER WARRANTY HOD W-1021 1.07 115.00 123.05
ARR01 WARR MANUFACTURER WARRANTY HOD W-1021 0.79 115.00 90.85
ARR01 WARR MANUFACTURER WARRANTY HOD W-1021 2.98 115.00 342.70
ARR01 WARR MANUFACTURER WARRANTY HOD W-1021 0.08 115.00 9.20
ARR01 WARR MANUFACTURER WARRANTY HOD W-1021 1.94 115.00 223.10
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.10 115.00 11.50
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.00 115.00 0.00
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.48 115.00 55.20
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.02 115.00 2.30
ARR04 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.00 115.00 0.00
*****

```

Continued on page 3

Work Order : 11152B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.00  115.00  0.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.10  115.00  11.50
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.44  115.00  50.60
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.06  115.00  6.90
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  115.00  57.50
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
W      1021          0.00   998.20   0.00   0.00   0.00   998.20
      Totals          0.00   998.20   0.00   0.00   0.00   998.20
*****
```

&k2S
&k0S