



Warranty Claim Form

Date: 2/17/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573FR3127S3351516
Reflection 260RD
Retail Purchase Date: null
Work Started: 1/22/2025
Work Completed: 1/22/2025

Claim Status: Paid
Dealer Work Order #: 11296B
Unit Offline Date: 9/16/2024

Claim #: 871093
Labor: \$218.50
Parts: \$0.00
Shipping: \$0.00
Total: \$218.50

Notes: JPH 1-23-25

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenewayrv.com
Approved Labor Rate: \$115.00

Customer Information

Operation Line # 1

Flat Rate Code: 620004 Floor Covering - Repair Linoleum (per *Fault Code:* Damaged/Maintenance sq. yd.)

Problem: The linoleum next to the bed door side has come loose and lifted.

Hours: .5

Cause: From manufacturer that way.

Amount: 57.50

Remedy: Used lino glue to glue it back down.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 510007 Metal - Touch-Up (Repair)

Fault Code: Damaged/Maintenance

Problem: Next to the door on the exterior, there are 3 spots right down to the metal.

Hours: .3

Cause: Scratches from factory.

Amount: 34.50

Remedy: Used black paint pen to cover the 3 small square scratches.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 3

Flat Rate Code: 540012 Sealing - Gutter Rail (Roof Line) *Fault Code:* Improper Installation/Build Molding

Problem: *Unsure on labor code* Roof needs dicor.

Hours: .8

Cause: Came from manufacturer this way.

Amount: 92.00

Remedy: Cleaned areas then sealed over the popped bubbles and gaps.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 4

Flat Rate Code: 550011 Metal Walls - Touch-Up (Repair)

Fault Code: Damaged/Maintenance

Problem: Large globs of silicone on the exterior of the unit.

Hours: .3

Cause: From manufacturer.

Amount: 34.50

Remedy: Cleaned away with solvent.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: