

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11301

Date In:	02 OCT 24	Author:	MGRAY
Promised Date:	31 OCT 24	Stock No:	11059
:	:	Year:	2024
Customer Name:	4775 - GOTTER, BETH	Manufacturer:	FOREST RIVER
Address:	404 SOUTH PEARL STREET	Brand:	FLAGSTAFF SUPER-LITE T
:	SPENCER, WI	Model:	26RBWS
Postal/Zip:	54479	Miles/Hrs:	:
Phone#(res):	:	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	26 JUN 24	:	:
Delivery Date:	28 JUN 24	:	:
InService Date:	:	:	:
Serial#:	4X4TFLB23RZ191556	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
1      COMPLAINT:  RECALL 51-1798 - REFER FOR VENTING CUT   W    1021   FORES
        CAUSE:      Recall. Cut vent holes in fridge
        CORRECTION: Done. request .50 labor
2      COMPLAINT:  HANDLE DORDERED AT ST IS RECIEVED AND   E    4775   GOTTE
        CAUSE:      1001 CUSTOMER REQUESTED.  Installed
        CORRECTION: Done.
3      COMPLAINT:  CUSTOMER STATES THAT THE REAR ODS REAR   W    1021   FORES
        CAUSE:      Light polarity was wired backwards,
        UTILITY LIGHT DOES NOT WORK-
        burned out switch in light, LED still
        works with an aux power source.
        Fixture needs replacement per warranty
        (30min)
        CORRECTION: Replaced light with identical fixture.
        Working as it should now. request .50
        labor
4      COMPLAINT:  CUSTOMER STATES THAT THERE ARE NO       W    1021   FORES
        CHANNELS ON THE TV AND THERE IS POOR
        RADIO CONNECTION- ***JESSE DID RUN
        MULTIPLE CHANNEL SCANS AND PICKED UP
        NONE, STATED THAT THERE IS NO
        CONNECTIONS AVAILABLE***
        CAUSE:      Stated Weak signal strenth, bad Winegard
        360 Antenna.  Used process of
        elimination one component at a time.
```

Continued on page 2

Work Order : 11301

 Job # Description JOB INFORMATION Type Bill To

 Eventually got some channels to show up
 during scan. It was down to both the TV
 or the Antenna. Used a different
 antenna to test, Winegard 360 +5G
 antenna is defective. Need to replace
 antenna through warranty.
 CORRECTION: ... request 2.50 hours
 5 CUSTOMER REQUESTS HAVING A BUG SCREEN INSTALLED ON E 4775 GOTTE
 THEIR WATER HEATER-

 Job # Part No Description PARTS Bill to Qty Price Total

 3 822020341 LIGHT PORCH LED OVAL W/S W-1021 1 5.77 5.77
 4 810089872685 HANDRAIL FOR STEP ABOVE W-1021 1 78.72 78.72
 4 615798406943 Winegard AR2-5G1 Air 360 W-1021 0 203.13 0.00

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 1 Z992 MISC LABOUR CODE (WARR JGK W-1021 0.50 115.00 57.50
 2 Z990 MISC LABOUR CODE (EXTE JGK E-4775 0.50 140.00 70.00
 3 WARR MANUFACTURER WARRANTY RW W-1021 0.50 115.00 57.50
 4 WARR MANUFACTURER WARRANTY RW W-1021 0.00 115.00 0.00
 5 Z990 MISC LABOUR CODE (EXTE E-4775 0.00 140.00 0.00
 4 WARR MANUFACTURER WARRANTY RW W-1021 0.50 115.00 57.50
 4 A440 ANTENNA, TV (ROOF MOUN W-1021 0.00 115.00 0.00

 Job # Excode Description EXTRAS bill to Qty Price Total

 1 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 5.25 5.25

 BILLINGS SUMMARY
 Type Bill Id Parts Labour Sublet Extras Tax Total

 E 4775 0.00 70.00 0.00 0.00 3.85 73.85
 W 1021 84.49 172.50 0.00 5.25 0.00 262.24
 Totals 84.49 242.50 0.00 5.25 3.85 336.09

&k2S
 &k0S