

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11307

Date In: 02 OCT 24 Author: MZYWICKI
Promised Date: 03 JUN 25 Stock No: 11162
: Year: 2024
Customer Name: 89064 - HALLAS, MARCIA Manufacturer: GRAND DESIGN
Address: 207969 JONES VALLEY RO Brand: TRANSCEND XPLOR
: MOSINEE, WI Model: 321BH
Postal/Zip: 54455 Miles/Hrs: 0
Phone#(res): Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: 6/3
Purchased Date: 10 MAY 24 :
Delivery Date: 17 JUL 24 :
InService Date: :
Serial#: 573TT372XR8832191 :

Job # Description JOB INFORMATION Type Bill To

1 CUSTOMER REQUESTS A SERVICE CALL TO THEIR UNIT AT E 89064 HALLA
BUCK SNORT RESORT SITE# 4
2 COMPLAINT: CUSTOMER STATES THAT THE MASTER LOCKS ON W 1020 GRAND
THE GLASS DOORS ARE NO LONGER LOCKING.
CUSTOMER STATED THAT THEY HAD HAD THE
BACK ONE LOCKED FOR A WHILE AND UNLOCKED
IT ONE DAY TO USE IT BUT THEN IT WILL
NOT LOCK AGAIN AFTER THAT. THEY ALSO
STATED THAT THE FRONT GLASS DOOR IS
HAVING ISSUES WITH THE LATCH CATCHING
AND NOT WANTING TO LOCK. WOULD LIKE TO
BE LOOKED AT AND FIXED IF POSSIBLE
CAUSE: pics and measurements taken What I found
is the framework on rear entry door by
striker plate is bent not allowing the
rear entry door to LATCH.
,,,,, I had no cell service to clock in
,,,,,
CORRECTION: remove the rear entry door cleaned wall
exterior surfaces uses butyl tape on
frame work of new entry door installed
and used silicone around edges of
framework I also had put new keys on
door side rear bumper
3 COMPLAINT: CUSTOMER STATES THAT THE DRAWER GLIDE IS W 1020 GRAND
BROKEN AND WILL NEED TO BE REPLACED. THE
CUSTOMER STATED THAT THEY BELIEVE IT IS
28" LONG

Continued on page 2

Work Order : 11307

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
      CAUSE:           in kitchen area drawer glides broken
      CORRECTION: pull out drawer and replaced the broken
                    glides REQUESTING .2 APPROVED .2
*****

```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty   Price   Total
*****
3     82201257  BRACKET CABINET MEMBER ONLY W-1020       1     9.87    9.87
3     822061256  BRACKET DRAWER MEMBER ONLY  W-1020       1     3.25    3.25
2     822061433  DOOR ENTRANCE 28 X 72 RH BL W-1020       1   562.80  562.80
*****

```

```

*****
Job# Lab Code Description           LABOUR Mech Bill to   Hrs   Rate   Total
*****
3 Z990 MISC LABOUR CODE (EXTE JS W-1020   0.20  140.00  28.00
2 Z990 MISC LABOUR CODE (EXTE JS W-1020   0.10  140.00  14.00
2 Z992 MISC LABOUR CODE (WARR JS W-1020   1.00  140.00  140.00
*****

```

```

*****
Job # Excode Description           EXTRAS           bill to   Qty   Price   Total
*****
1 SC SERVICE CALL E-89064  119.00  3.75  446.25
1 SSE SHOP SUPPLIES - EXTERNAL E-89064  1.00  0.00  0.00
3 FRT FREIGHT FOR JOB 3 W-1020  1.00  14.19  14.19
3 FRT FREIGHT JOB 3 W-1020  1.00  14.16  14.16
2 FRT FREIGHT FOR JOB 2 GLASS EN W-1020  1.00  223.60  223.60
*****

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id   Parts   Labour   Sublet   Extras   Tax   Total
*****
E 89064         0.00    0.00    0.00   446.25  24.56  470.81
W 1020        575.92  182.00    0.00   251.95   0.00  1,009.87

Totals        575.92  182.00    0.00   698.20  24.56  1,480.68
*****

```

&k2S
&k0S