

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 2095735
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TFLX28RD456168
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 010 / 010B
 ITEM # FLT22FBS
 DEALER RO # 11318
 CLAIM START DATE 10/18/2024
 CLAIM END DATE 11/06/2024

Labor rate: \$115.00

OWNER INFORMATION

DOUG MALINSKY
 1931 E CARPENTER LAKE RD
 Eagle River, WI 54521
 USA

Retail Date of Purchase 10/02/2023 WARRANTY EXPIRATION DATE 10/02/2024

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
 30-91-01-00-000910 Computer Swing Table, Laptop Tray - Interior/Living Quarters, Sofa, Chair/
 Replace/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2024-10-18 11:36:38 :: Complaint: There is a lock on the table, the latch that locks the table in place was off the wall and on the floor. Cause: The lock that right underneath the tabletop that keeps it from moving fell off. Correction: Put the lock back together and reinstalled. It is a threaded piece, so it needs to be checked regularly to make sure it's not getting too loose. Additional Note : greeneway@dealer-advisors.com, 2024-10-18 11:46:14 :: Unit was in prior to warranty expiring, WO was created 10/2/24

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$57.50
 Serial# Appr Hrs 0.35 Appr Labor Amt \$40.25

Notes

Hello, please attach a copy of the dated work order that shows the creation date. thank you
 WO uploaded. Thank you.
 changed to correct code. kerb

Labor

Line# 2 Operation Code Operational Description
 30-101-02-00-001077 Hinged Passage Door Striker - Interior/Interior Doors/Adjust/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2024-10-18 11:38:51 :: Complaint: Bathroom door stays closed but doesn't latch so in travel the door is coming on. Cause: The latch on the frame was set too far back. Correction: Stuffed the old screw holes so the screws won't track into them, slid the latch forward, and put the screws in. The door stays latched now.

Model# Dlr Sub Hrs 0.10 Sub Labor Amt \$11.50
 Serial# Appr Hrs 0.10 Appr Labor Amt \$11.50

Notes

Kerb

Labor

Line# 3 Operation Code Operational Description
 70-147-01-11-003957 Connexx TV - Appliances/Television/Replace/Electrical

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2024-10-18 11:41:28 :: Complaint: Remote turns on the tv but will not do anything else. Put in new batteries but it is still not working. Cause: Faulty TV. The remote will turn on the TV but does nothing else. I took the remote and tried it on another connex TV in a different unit and everything works. Correction: R&R TV

Model# 1 Dlr Sub Hrs 1.50 Sub Labor Amt \$172.50

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.