

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11318

Date In: 02 OCT 24 Author: MGRAY
Promised Date: 14 OCT 24 Stock No: 10825
: Year: 2024
Customer Name: 17049 - MALINSKY, DOUG Manufacturer: FOREST RIVER
Address: 1931 E CARPENTER LAKE Brand: FLAGSTAFF MICRO-LITE
: EAGLE RIVER, WI Model: 22FBS
Postal/Zip: 54521 Miles/Hrs:
Phone#(res): 715-479-1723 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: DOUG.MALINSKY@GMAIL.CO Tag#:
Purchased Date: 12 SEP 23 :
Delivery Date: 02 OCT 23 :
InService Date: :
Serial#: 4X4TFLX28RD456168 :

Job # Description JOB INFORMATION Type Bill To

WS COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF E 17049 MALIN
CONTAINED - TOWABLE
CAUSE: 1001 CUSTOMER REQUESTED
CORRECTION: Done.
WARR COMPLAINT: THERE IS A LOCK ON THE TABLE LOCK. the W 1021 FORES
latch that locks the table in place was
off the wall and one the floor.
CAUSE: The lock that's right underneath the
table top that keeps it from moving fell
off. Their are three different locks on
each table, and I didn't know which one
was the issue at first so I checked the
locks on the left side and they were all
fine, checked the two on the right side
and they were good. I looked underneath
the table and I see that one of the
locks is missing. I found part of the
lock in between the couch cushions under
a pillow and another part underneath the
recliner. I put the lock back together.
It's a threaded piece so it needs to be
checked regularly to make sure it's not
getting too loose.
CORRECTION: Done.
WARR COMPLAINT: BATHROOM DOOR ISSUE - installed the door W 1021 FORES
previously. stays closed but doesn't
latch, so in travel the door is coming
on.

Continued on page 2

Work Order : 11318

```

*****
Job #   Description           JOB INFORMATION                               Type Bill To
*****
      CAUSE:      The latch on the frame was set too far
                   back. I stuffed the old screw holes so
                   the screws won't track into them, slid
                   the latch forward, and put the screws
                   in. The door stays latched now.

      CORRECTION: Done.

WARR    COMPLAINT: remote turns the tv son but will not do  W    1021    FORES
                   anything else. put new batteries in the
                   remote and still not working

      CAUSE:      Faulty tv. The remote will turn the TV
                   on, but literally nothing else. I took
                   the remote and tried it on another
                   connex TV in a different unit and
                   everything works. We will need a new tv.

      CORRECTION: ... REQUEST 1.5 HOURS OF LABOR

WARR    COMPLAINT: WARRANTY REPAIR 4 - WINDOW ON THE SLIDE  W    1020    GRAND
                   OUT HAS COME LOOSE FROM THE ARMS. WINDOW
                   BEHIND SEATING.

      CAUSE:      The mechanism that opens and closes the
                   window failed. I replaced the mechanism.

      CORRECTION: Done.

WARR    COMPLAINT: WARRANTY REPAIR 5 - SHADE ROD ABOVE THE  W    1020    GRAND
                   BED IS MISSING AN ENDCAP AND THEY CAUSES
                   THE ROD TO FALL OUT WHEN TRAVELING.

      CAUSE:      The window shade end cap is missing. I
                   can't find it anywhere, and we don't
                   have any on hand, so we will have to
                   order some. They are a tan/cream color.
                   See pictures

      CORRECTION: ... REQUEST .50 HOURS OF LABOR

1      TOP OFF LP                                           E    17049    MALIN
2      CAN WE REMOVE THE OK TO SHIP STICKER FROM FRAME?    E    17049    MALIN
3      WOULD LIKE RECOMMENDATION ON THE HITCH TO HELP WITH E    17049    MALIN
      SWAP ISSUES.

```

```

*****
Job # Part No      Description      PARTS    Bill to    Qty    Price    Total
*****
WS      071247312003 -50 ANTIFREEZE/ 1 GALLON E-17049    3      9.62     28.86
WARR0 82205002      4" WINDOW ARM SUPPORT W/ W-1020    1     23.60     23.60

```

```

*****
Job#  Lab Code  Description    LABOUR    Mech Bill to    Hrs    Rate    Total
*****
WS W495        WINTERIZE RV (WATER SY JGK  E-17049    0.18    140.00    25.20
ARR01 Z992     MISC LABOUR CODE (WARR JGK  W-1021    0.38    115.00    43.70
ARR02 Z992     MISC LABOUR CODE (WARR JGK  W-1021    0.50    115.00    57.50
ARR03 Z992     MISC LABOUR CODE (WARR JGK  W-1021    0.50    115.00    57.50

```

Continued on page 3

Work Order : 11318

```

*****
Job#  Lab Code  Description    LABOUR    Mech Bill to      Hrs      Rate      Total
*****
ARR04 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     115.00      0.00
ARR05 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.50     115.00     57.50
   3 Z990      MISC LABOUR CODE (EXTE      E-17049      0.00     130.00      0.00
   WS W495      WINTERIZE RV (WATER SY JGK E-17049      0.00     140.00      0.00
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00     115.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00     115.00      0.00
ARR03 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00     115.00      0.00
ARR04 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     115.00      0.00
ARR05 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     115.00      0.00
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.12     115.00     13.80
ARR04 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.50     115.00     57.50
   2 Z990      MISC LABOUR CODE (EXTE      E-17049      0.00     130.00      0.00
   WS W495      WINTERIZE RV (WATER SY JGK E-17049      0.13     140.00     18.20
   WS W495      WINTERIZE RV (WATER SY JGK E-17049      0.31     140.00     43.40
   WS W495      WINTERIZE RV (WATER SY JGK E-17049      0.08     140.00     11.20

```

```

*****
Job #  Excode    Description    EXTRAS      bill to      Qty      Price      Total
*****
   WS  SSE      SHOP SUPPLIES - EXTERNAL      E-17049      1.00        7.35        7.35
   WS  J-ADJ      QUOTE ADJUSTMENT      E-17049      1.00     -29.21     -29.21

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E   17049          28.86      98.00        0.00     -21.86        5.80     110.80
W   1020          23.60     115.00        0.00        0.00        0.00     138.60
W   1021           0.00     172.50        0.00        0.00        0.00     172.50

      Totals          52.46     385.50        0.00     -21.86        5.80     421.90

```

&k2S
&k0S