

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11420B

Date In:	25 FEB 25	Author:	KOTT
Promised Date:	04 JUL 25	Stock No:	11249
:	:	Year:	2025
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	PUMA TT
:	WISCONSIN RAPIDS, WI	Model:	31QBBH
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	28 MAR 25	:	:
Delivery Date:	17 APR 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUG24SP103689	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - finish missing from W    1021    FORES
        bottom of bunk rooms door
        CAUSE:      Scraped finish
        CORRECTION: Used black paint pen to cover the ecrape
        ***PLEASE REQUEST .30 HOURS OF LABOR***
        APPROVED .20 HOURS FLAT RATE
WARR    COMPLAINT:  WARRANTY REPAIR 3 - AC has something      W    1021    FORES
        rattling inside the main AC shroud
        inside
        CAUSE:      Flapping aluminum tape causing noise in
        the AC
        CORRECTION: Removed 6 screws holding ac interior
        shroud in place then pressed the
        aluminum tape firmly into place
        reinstalled the shroud tested and no
        longer making annoying rattling noise
        ****REQUEST .75 HOURS OF LABOR****
        APPROVED .30 HOURS FLAT RATE
WARR    COMPLAINT:  WARRANTY REPAIR 2 - all passage doors      W    1021    FORES
        have heavy smear marks on them
        CAUSE:      Smears on door faces
        CORRECTION: Used a strong solution of Murphy's soap
        and scrubbed both sides of 3 doors down
        the smears are no longer there
        ***REQUEST 1.5 HOURS OF LABOR***
        APPROVED .80 HOURS FLATE RATE OF .10X8
1        COMPLAINT:  FOUND ON PREP- THE REAR BUNK SLIDE IS      W    1021    FORES
        OUT OF SQUARE IN THE SLIDEOUT HOLE
*****
```

Continued on page 2

Work Order : 11420B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
      CAUSE:      Slide is definitely out of square in
                  slide opening. Looks like bracket
                  shifted holding one of the slide racks
                  in position. Requires adjustments (2hrs)
      CORRECTION: Made incremental adjustments to the rail
                  brackets, didn't seem to affect the
                  slide position, those mostly control the
                  "tip-in," angle. Measured from corner to
                  corner on interior of slide. Slide room
                  from interior measures 1-1/4"
                  out-of-square. Not alot we can do to
                  adjust this aside from pulling the whole
                  slide and swimming the warebar that the
                  slide sits on. As of right now all the
                  seals are touching and sealing
                  appropriately. Noting issue and
                  diagnostics for any future use.
WARR    COMPLAINT: WARRANTY REPAIR 4 - THERE ARE TWO           W      1021    FORES
                  CORNERS IN THE BUNK ROOM WHERE THE
                  SEAL/SEAM HAS A LIP TO IT
      CAUSE:      Rubber trim in bunk corner not laying
                  appropriately.
      CORRECTION: Glued and used white silicone to improve
                  the cosmetic appeal of the corner trim
                  seal.

```

```

*****
Job#  Lab Code  Description    LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50    115.00    57.50
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50    115.00    57.50
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50    115.00    57.50
      1 WARR      MANUFACTURER WARRANTY RW W-1021    0.00    115.00     0.00
      1 WARR      MANUFACTURER WARRANTY TD W-1021    0.35    115.00    40.25
ARR04 Z992      MISC LABOUR CODE (WARR RW W-1021    0.37    115.00    42.55
      1 WARR      MANUFACTURER WARRANTY RW W-1021    0.15    115.00    17.25
ARR04 Z992      MISC LABOUR CODE (WARR RW W-1021    0.13    115.00    14.95

```

```

*****
Job #  Excode    Description    EXTRAS    bill to    Qty    Price    Total
*****
ARR01  SSE        SHOP SUPPLIES - EXTERNAL W-1021    1.00     0.00     0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id    Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1021      0.00     287.50     0.00     0.00     287.50

```

Continued on page 3

Work Order : 11420B

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	0.00	287.50	0.00	0.00	0.00	287.50

&k2S
&k0S