

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11420B

Date In:	25 FEB 25	Author:	KOTT
Promised Date:	04 JUL 25	Stock No:	11249
:	:	Year:	2025
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	PUMA TT
:	WISCONSIN RAPIDS, WI	Model:	31QBBH
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4TPUG24SP103689	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - finish missing from W    1021    FORES
        bottom of bunk rooms door
        CAUSE:      Scraped finish
        CORRECTION: Used black paint pen to cover the ecrape
        ***PLEASE REQUEST .30 HOURS OF LABOR***
WARR    COMPLAINT:  WARRANTY REPAIR 3 - AC has something W    1021    FORES
        rattling inside the main AC shroud
        inside
        CAUSE:      Flapping aluminum tape causing noise in
        the AC
        CORRECTION: Removed 6 screws holding ac interior
        shroud in place then pressed the
        aluminum tape firmly into place
        reinstalled the shroud tested and no
        longer making annoying rattling noise
        ****REQUEST .75 HOURS OF LABOR****
WARR    COMPLAINT:  WARRANTY REPAIR 2 - all passage doors W    1021    FORES
        have heavy smear marks on them
        CAUSE:      Smears on door faces
        CORRECTION: Used a strong solution of Murphy's soap
        and scrubbed both sides of 3 doors down
        the smears are no longer there
        ***REQUEST 1.5 HOURS OF LABOR***
1       COMPLAINT:  FOUND ON PREP- THE REAR BUNK SLIDE IS W    1021    FORES
        OUT OF SQUARE IN THE SLIDEOUT HOLE
        CAUSE:      Rear ods slide is out of square in hole.
        Will need to adjust slide at the rams.
        Pics uploaded.
```

Continued on page 2

Work Order : 11420B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
CORRECTION: ... ***REQUEST 1.5 HOURS OF LABOR***
WARR      COMPLAINT:  WARRANTY REPAIR 4 - THERE ARE TWO          W      1021      FORES
              CORNERS IN THE BUNK ROOM WHERE THE
              SEAL/SEAM HAS A LIP TO IT
      CAUSE:      TWO OF THE CORNERS IN THE BUNK ROOM NEED
              TO BE TRIMED AND HAVE SILICONE PUT OVER
              THEM
      CORRECTION: *****REQUEST .75 HOURS OF LABOR*****

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.50  115.00  57.50
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.50  115.00  57.50
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.50  115.00  57.50
      1 WARR      MANUFACTURER WARRANTY  TD  W-1021      0.00  115.00   0.00
      1 WARR      MANUFACTURER WARRANTY  TD  W-1021      0.35  115.00  40.25
ARR04 Z992      MISC LABOUR CODE (WARR      W-1021      0.00  115.00   0.00

```

```

*****
Job #  Excode   Description  EXTRAS      bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021      1.00   0.00   0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      0.00      212.75      0.00      0.00      0.00      212.75

      Totals      0.00      212.75      0.00      0.00      0.00      212.75

```

&k2S
&k0S