



Warranty Claim Form

Date: 4/10/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3323S3351753
Reflection 27BH
Retail Purchase Date: null
Work Started: 3/31/2025
Work Completed: 3/31/2025

Claim Status: Paid
Dealer Work Order #: 11500B
Unit Offline Date: 10/15/2024

Claim #: 886344
Labor: \$138.00
Parts: \$123.88
Shipping: \$31.19
Total: \$293.07

Notes: Sg 2/7/25 Need copy of DAF

Dealer Information

Customer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Operation Line # 1

Flat Rate Code: 580011 Slider/Crank Out Windows - R&R Window *Fault Code:* Improper Installation/Build Assembly

Problem: DS window in bedroom has a chip out of the glass.

Hours: 1

Cause: Chipped by MFG.

Amount: 115.00

Remedy: Replace window. Rough opening is 30" by 22 1/2"

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
580941 WINDOW 8800 DW 30 X 22 G20 TP BK	WINDOW 8800 DW 30 X 22 G20 TP BK		1	1	123.88

Operation Line # 2

Flat Rate Code: 610011 Moldings/Trims - Repair (per Piece) *Fault Code:* Improper Installation/Build

Problem: Trim in bathroom in corner under med cabinet is loose.

Hours: .2

Cause: Loose from mfg.

Amount: 23.00

Remedy: Used nail gun to secure better.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: