

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497  
 GREENEWAY INC  
 DBA GREENEWAY RV SALES & SERVICE  
 8220 STATE HWY 13 SOUTH  
 WISCONSIN RAPIDS, WI 54494  
 USA

CLAIM STATUS Paid  
 CLAIM 2299716  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4TPUS29SP104036  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 420 / 420  
 ITEM # PUT403LFT  
 DEALER RO # 11551B  
 CLAIM START DATE 05/15/2025  
 CLAIM END DATE 05/15/2025

Labor rate: \$140.00

**OWNER INFORMATION**

DANIEL RITZOW  
 N94W1992 Victory Road  
 Menomonee Falls, WI 53051  
 USA

Retail Date of Purchase 11/08/2024

WARRANTY EXPIRATION DATE

11/08/2025

**Claim Line Details**

**Labor**

Line# 1      **Operation Code**      **Operational Description**  
 20-46-24-00-000721      Window - Exterior/Windows/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-05-15 09:44:42 :: Expired Claim 2118231 Complaint:  
 There is silicone on almost every window. Cause: Silicone is smeared on all the windows from factory.  
 Correction: Cleaned silicone off the windows.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.50	<b>Sub Labor Amt</b>	\$70.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.50	<b>Appr Labor Amt</b>	\$70.00

**Notes**  
 per expired claim 2118231

**Labor**

Line# 2      **Operation Code**      **Operational Description**  
 70-148-01-00-001714      Radio Remote - Appliances/Radio/Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-05-15 09:46:00 :: Previous PA 2118231 expired  
 Complaint: Remote for the fireplace does not work. Cause: Remote is inoperable and does not work. Correction:  
 R&R remote for fireplace.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.00	<b>Sub Labor Amt</b>	\$0.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.00	<b>Appr Labor Amt</b>	\$0.00

**Notes**

**Part**

Line# 1      **Item #**      **Description**  
 F100157418      FIREPLACE PARTS, REMOTE, F31-18A, F32-18A, F36-18A, F40-18A,  
 F4716W

<b>Model #</b>	<b>Serial #</b>		<b>Part tag</b>	0000365927	
<b>Sub Qty</b>	1.00	<b>Sub Dlr Price</b>	\$35.07	<b>Sub Freight</b>	\$21.15
<b>Appr Qty</b>	1.00	<b>Appr Dlr Price</b>	\$35.07	<b>Appr Freight</b>	\$21.15

**Notes**

**Labor**

Line# 3      **Operation Code**      **Operational Description**  
 30-102-24-00-001101      Slide Out Fascia, each section - Interior/Panels, Ceilings, & Interior Moldings/  
 Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-05-15 09:46:45 :: Complaint: The left fascia board pulled

