

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11551B

Date In:	09 NOV 24	Author:	KOTT
Promised Date:	25 DEC 24	Stock No:	11236
:	:	Year:	2025
Customer Name:	17513 - RITZOW, DANIEL	Manufacturer:	FOREST RIVER
Address:	N94W19982 VICTORY ROAD	Brand:	PUMA DESTINATION
:	MENOMONEE FALLS, WI	Model:	403LFT
Postal/Zip:	53051	Miles/Hrs:	0
Phone#(res):	262-875-7925	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	04 OCT 24	:	:
Delivery Date:	08 NOV 24	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS29SP104036	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - the grey. 2 which is W    1021    FORES
        kitchen is not reading correctly and
        CAUSE:       This is the 3rd unit with this issue
        need to drop belly then fresh tank add a
        CORRECTION: Found that unit must be perfectly level
        for the long small diameter pipe to
        drain into tank correctly
WARR    COMPLAINT:  WARRANTY REPAIR 2 - silicone on almost    W    1021    FORES
        every window
        CAUSE:       Silicone smeared on windows
        CORRECTION: Cleaned silicone off the windows
WARR    COMPLAINT:  WARRANTY REPAIR 3 - remote for fireplace W    1021    FORES
        is in op
        CAUSE:       Remote for fireplace is inop Please
        order new remote for fireplace photos of
        model and such are attached
        CORRECTION: . REQUEST .50 AND REMOTE
WARR    COMPLAINT:  WARRANTY REPAIR 4 - the left fascia      W    1021    FORES
        board is pulled away from slideroom
        CAUSE:       The slide arm busted loose the screws
        were pulled out and bent
        CORRECTION: Removed decor panel from over the fascia
        arms wood removed the trim on wall and
        outer edge of slide arms fascia removed
        the header fascia. Found the wood pulled
        away with the screws bent removed screws
```

Continued on page 2

Work Order : 11551B

Job # Description JOB INFORMATION Type Bill To

then pried away the rubber that is
 wrapped around outer edge of the board .
 Removed all staples and nails from trim
 ,fascia decor panels ,and Fascia
 boards. Positioned the board back in
 place and used longer screws to re
 secured the fascia board then re secured
 rubber around outer edge of the board
 installed the decor panels to the header
 fascia and arm fascia installed the trim
 on wall and outer edge of the slide arm.
 Used nail set to set some nails then
 filled with putty and used black paint
 pen to touch up a few spots

Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

ARR01	Z992	MISC LABOUR CODE (WARR HOD W-1021	0.00	115.00	0.00
ARR01	Z992	MISC LABOUR CODE (WARR HOD W-1021	0.02	115.00	2.30
ARR01	Z992	MISC LABOUR CODE (WARR HOD W-1021	0.48	115.00	55.20
ARR01	Z992	MISC LABOUR CODE (WARR HOD W-1021	0.00	115.00	0.00
ARR02	Z992	MISC LABOUR CODE (WARR HOD W-1021	0.16	115.00	18.40
ARR02	Z992	MISC LABOUR CODE (WARR HOD W-1021	0.34	115.00	39.10
ARR03	Z992	MISC LABOUR CODE (WARR HOD W-1021	0.50	115.00	57.50
ARR04	Z992	MISC LABOUR CODE (WARR HOD W-1021	0.43	115.00	49.45
ARR04	Z992	MISC LABOUR CODE (WARR HOD W-1021	0.33	115.00	37.95
ARR04	Z992	MISC LABOUR CODE (WARR HOD W-1021	1.00	115.00	115.00
ARR04	Z992	MISC LABOUR CODE (WARR HOD W-1021	0.34	115.00	39.10

Job # Excode Description EXTRAS bill to Qty Price Total

ARR01	SSE	SHOP SUPPLIES - EXTERNAL	W-1021	1.00	0.00	0.00
ARR01	M	1 1/2" PVC PIPE	W-1021	2.00	6.50	13.00

BILLINGS SUMMARY

Type Bill Id Parts Labour Sublet Extras Tax Total

W	1021	0.00	414.00	0.00	13.00	0.00	427.00
Totals		0.00	414.00	0.00	13.00	0.00	427.00

&k2S

&k0S