

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 2191100
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TPU821SP104054
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 420 / 420
 ITEM # PUT429LFT
 DEALER RO # 11579B
 CLAIM START DATE 02/04/2025
 CLAIM END DATE 02/06/2025

Labor rate: \$115.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-103-04-00-001119 Carpet - Interior/Flooring/Clean/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-02-04 14:47:42 :: Complaint: Slide room fabric flooring has stains on it both bunk and living room slides. Cause: From factory. Correction: Used cleaner to remove the stains in the fabric.

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$57.50
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$57.50

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 20-46-24-00-000721 Window - Exterior/Windows/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-02-04 14:49:17 :: Complaint: The high upper windows have silicone smeared on interior and exterior of windows. Cause: From factory. Correction: Used quik solve to remove the silicone from windows then cleaned with window cleaner- all upper windows. 5 Total.

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$57.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$34.50

Notes
flat rate

Labor

Line# 3 **Operation Code** **Operational Description**
 30-101-24-00-001078 Sliding, Pocket Door - Interior/Interior Doors/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-02-04 14:50:34 :: Complaint: Finish on the dark wood door you can see smear marks on all 5 passage doors on both sides in this unit. Cause: From manufacturer. Correction: Used murphy's oil soap to clean down each door.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$34.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$34.50

Notes

Labor

Line# 4 **Operation Code** **Operational Description**
 60-141-24-00-001602 Fiberglass Tub, Shower Surround - Plumbing/Shower, Tub Surround/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-02-04 14:51:51 :: Complaint: Black scratch in floor of rear tub and scuffs in shower base in front bath. Cause: From manufacturer. Correction: Used quick solve to remove

the black scratches.

Model#

Dir Sub Hrs 0.70

Sub Labor Amt \$80.50

Serial#

Appr Hrs 0.20

Appr Labor Amt \$23.00

Notes

flat rate

Submitted

Labor Amt \$230.00
Parts & Freight \$0.00
Total \$230.00

Approved

Labor Amt \$149.50
Parts & Freight \$0.00
Total \$149.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.