

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11588B

Date In: 22 JAN 25 Author: KOTT
Promised Date: 04 JUL 25 Stock No: 11292
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: FLAGSTAFF SUPER-LITE T
: WISCONSIN RAPIDS, WI Model: 26FKBS
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#:
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 4X4TFLB20SZ195411 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - Microwave Arks when W 1021 FORES
being used
CAUSE: Microwave arks when in use The microwave
arc's. I walked out on the lot and
replaced the microwave. I broke down
and threw away the box when I was done
and put the old microwave in the
warranty cage.
CORRECTION: ... Done.
WARR COMPLAINT: WARRANTY REPAIR 2 - Bathroom door would W 1021 FORES
not open and shut
CAUSE: Bedroom door would not open and close
properly due to excessive adhesive glue
behind door jam The first repair did not
fix the issue. The door latch is
catching the striker plate. I removed
the striker plate, door jam, and I used
my router to cut out an area around the
striker plate so the latch would clear.
The manufacturer just had a piece of
tape covering multiple holes that they
cut in the stud for the latch. I routed
out the hole and painted it. I cleaned
the old sealant and 3m tape from the
door jam and stud, put new 3m tape on
and added a screw to the top and bottom
of the door jam. The black striker
plate is scratched pretty bad and needs

Continued on page 2

Work Order : 11588B

Job #	Description	JOB INFORMATION	Type	Bill To
-------	-------------	-----------------	------	---------

replacement.

CORRECTION: Took off door jam trimmed excessive adhesive put back on with 3mill double sided tape door now open and closes properly ...

WARR	COMPLAINT:	WARRANTY REPAIR 3 - Putty ground in to carpet on slide under table	W	1021 FORES
------	------------	--	---	------------

CAUSE: Putty smashed in carpet The manufacturer ground putty into the slide rug, and it can't be removed by cleaning it. I removed the kitchen table and cushions from the dinette benches, removed the panels in the back rests, pulled all the screws, disconnected 120 volt wires, and removed the benches I took the screws out of the recliners' frames and pulled the recliners out of the slide. I removed the baton strips and pulled the nails and staples. The edges of the rug are tucked under the facia and the manufacturer used some sort of sealant to hold the facia on so I had to carefully pry up in the bottom of the facia boards and fillet the sealant off. I got the bottom two feet of facia loosened up, and I pulled the rug out from underneath them. The rug is under the wall in some places, and other places are flush with the wall. I cut around the lag bolts, 120 volt wiring, and along the wall where the rug is tucked. I removed the rug and removed it or pounded in the staples that held it in place. Once I got the rug out, I laid it out by the new one, and I can see the new one is considerably shorter. I put the dinette benches and recliners back in the slide until the right rug is sent. We got the new rug, I cut it to size, laid it out in the slide out and stapled it down. I put the benches back in, nailed the batons back down and i had to cut and install two more. I puttied the holes, put the recliners back in place and secured them to the floor. I swept put the unit when I was done. I had no room inside the building, so I started working on it outside. Once a bay opened up, I closed

Continued on page 3

Work Order : 11588B

the unit up and brought it in. Halfway through removing the benches, the salesman decided to show it, so I had to stop working on it and didn't have anything else to punch into.

CORRECTION: Will need new carpet 15ft by 4ft Done.

```
*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
WARR0 82202582 MICROWAVE - PFL: MAGIC CHEF, W-1021 1 188.59 188.59
WARR0 82204693 CARPET RUNNER - PFL: 20051 T W-1021 1 186.64 186.64
WARR0 82200870 BATTEN MONTE RIDGE 7/8 X 8' W-1021 1 2.11 2.11
*****
```

```
*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR JT W-1021 0.45 115.00 51.75
ARR01 Z992 MISC LABOUR CODE (WARR JT W-1021 0.05 115.00 5.75
ARR01 WARR MANUFACTURER WARRANTY JGK W-1021 0.50 115.00 57.50
ARR02 Z992 MISC LABOUR CODE (WARR JT W-1021 0.50 115.00 57.50
ARR02 WARR MANUFACTURER WARRANTY JGK W-1021 0.00 115.00 0.00
ARR02 WARR MANUFACTURER WARRANTY JGK W-1021 0.25 115.00 28.75
ARR02 WARR MANUFACTURER WARRANTY JGK W-1021 0.25 115.00 28.75
ARR03 Z992 MISC LABOUR CODE (WARR JT W-1021 0.42 115.00 48.30
ARR03 Z992 MISC LABOUR CODE (WARR JT W-1021 0.08 115.00 9.20
ARR03 WARR MANUFACTURER WARRANTY JGK W-1021 2.71 115.00 311.65
ARR03 WARR MANUFACTURER WARRANTY JGK W-1021 0.08 115.00 9.20
ARR03 WARR MANUFACTURER WARRANTY JGK W-1021 0.03 115.00 3.45
ARR03 WARR MANUFACTURER WARRANTY JGK W-1021 2.18 115.00 250.70
ARR03 WARR MANUFACTURER WARRANTY JGK W-1021 0.00 140.00 0.00
ARR03 WARR MANUFACTURER WARRANTY JGK W-1021 0.50 140.00 70.00
ARR03 WARR MANUFACTURER WARRANTY JGK W-1021 0.00 140.00 0.00
ARR03 WARR MANUFACTURER WARRANTY JGK W-1021 0.00 140.00 0.00
*****
```

```
*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
ARR01 FRT FREIGHT FOR CARPET AND MIC W-1021 1.00 64.61 64.61
ARR03 FRT FREIGHT FOR SECOND CARPET W-1021 0.00 0.00 0.00
ARR03 FRT FREIGHT FOR BATTEN W-1021 1.00 115.25 115.25
*****
```

BILLINGS SUMMARY

```

Type Bill Id Parts Labour Sublet Extras Tax Total
*****
W 1021 377.34 932.50 0.00 179.86 0.00 1,489.70
Totals 377.34 932.50 0.00 179.86 0.00 1,489.70
*****
```

Continued on page 4

Work Order : 11588B

&k2S
&k0S