



Warranty Claim Form

Date: 2/17/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573FS372XSAA20617
Solitude 3203GK
Retail Purchase Date: null
Work Started: 1/17/2025
Work Completed: 1/17/2025

Claim Status: Paid
Dealer Work Order #: 11630B
Unit Offline Date: 12/18/2024

Claim #: 872110
Labor: \$92.00
Parts: \$0.00
Shipping: \$0.00
Total: \$92.00

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenewayrv.com
Approved Labor Rate: \$115.00

Customer Information

Operation Line # 1

Flat Rate Code: 330005 Fittings (Elbows, T's, Connections) - *Fault Code:* Improper Installation/Build Tighten/Secure

Problem: Puddle of water beneath kitchen sink.

Hours: .3

Cause: Loose fitting beneath kitchen sink.

Amount: 34.50

Remedy: Unthreaded the fitting, wiped the fitting and what it screws onto. Carefully threaded back into place and used plumbers wrench to snug it up. Tested by running water for 10 minutes, no leaks.

Sublet Repairs:
\$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 620004 Floor Covering - Repair Linoleum (per *Fault Code:* Improper Installation/Build sq. yd.)

Problem: Lino at rear of unit has a scratch in it from slideroom.

Hours: .5

Cause: Manufacturing scratch.

Amount: 57.50

Remedy: Used very fine sandpaper and water to sand over the scratch. Before and after pictures uploaded.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: