

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11638

Date In:	09 JAN 25	Author:	MGRAY
Promised Date:	31 MAY 25	Stock No:	
:		Year:	2018
Customer Name:	113975 - KRIMMER, DANI	Manufacturer:	GRAND DESIGN
Address:	P4529 SPORTSMAN DR	Brand:	IMAGINE
:	BIRNAMWOOD, WI	Model:	2400BH
Postal/Zip:	54414	Miles/Hrs:	
Phone#(res):	715-370-3275	Exterior Color:	
Phone#(bus):		Unit Type:	
Cell Phone:		License#:	
Email:	DCTREES@HOTMAIL.COM	Tag#:	RYAN db :1/23 spoke w/
Purchased Date:		:	
Delivery Date:		:	
InService Date:		:	
Serial#:	573TE2926J6605579	:	

Job #	Description	JOB INFORMATION	Type	Bill To
1	COMPLAINT:	the slide out on the unit is not coming out properly. one side seems to not go out at all while the other side is trying to go out. worked fine when used the last time, then once the unit got brought home, he tried to get the slide out to get his personal items out of the unit and the slide would no longer open for him. would like looked at for diagnostic.	E	113975 KRIMM
	CAUSE:	Slide ran completely fine when tested here in the shop. When, where, was the problem? Location? Was unit on level ground? Were slide seals frozen? After inspecting slide, noticed an outline on slide roof. Looks like an object was sitting on slide roof at one point. Did an object get placed on slide roof when it was closed? That will cause it to not open.		
	CORRECTION:	No issue with slide operation found. Is functioning as expected, in an out evenly, cycled 4 times. Used slide out seal conditioner on both side whipe-seals.		
2	COMPLAINT:	recall 22v-308 - lp regulator defect. paperwork attached for the recall and repair.	- W	1020 GRAND

Continued on page 2

Work Order : 11638

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
      CAUSE:      Regulator replaced per recall. One
                  pigtail also replaced. Rubber cracking
                  and didn't match other pigtail, unsure
                  why that one was used.
      CORRECTION: Replaced regulator and a pigtail. Tested
                  for leaks and pressure set.

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
2      815505013253 AUTO CHANGE OVER REG.      W-1020      1      80.03      80.03
2      815505012683 18" RV TYPE 1 PIGTAIL-PK W-1020      1      25.43      25.43

```

```

*****
Job# Lab Code      Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
1 DIAG      DIAGNOSTICS      RW      E-113975      0.29      140.00      40.60
2 Z992      MISC LABOUR CODE (WARR RW      W-1020      0.50      115.00      57.50
1 DIAG      DIAGNOSTICS      RW      E-113975      0.27      140.00      37.80
1 DIAG      DIAGNOSTICS      RW      E-113975      0.44      140.00      61.60
2 Z992      MISC LABOUR CODE (WARR RW      W-1020      0.02      115.00      2.30
2 Z992      MISC LABOUR CODE (WARR RW      W-1020      0.48      115.00      55.20

```

```

*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
1 SSE      SHOP SUPPLIES - EXTERNAL      E-113975      1.00      10.50      10.50

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E      113975      0.00      140.00      0.00      10.50      8.30      158.80
W      1020      105.46      115.00      0.00      0.00      0.00      220.46

      Totals      105.46      255.00      0.00      10.50      8.30      379.26

```

&k2S
&k0S