

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11694

Date In: 22 JAN 25 Author: KOTT
Promised Date: 25 DEC 25 Stock No: 11264
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: PUMA CAMPING EDITION
: WISCONSIN RAPIDS, WI Model: 283BHCE
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: SOLD TO BROCK
Purchased Date: 15 MAR 25 :
Delivery Date: 04 APR 25 :
InService Date: :
Serial#: 5ZT2PUTB7S4023102 :

Job # Description JOB INFORMATION Type Bill To

NTTS COMPLAINT: NEW TRAVEL TRAILER STOCK PREP I PDI PRE-D
CAUSE: New unit
CORRECTION: Prepped unit
CIN COMPLAINT: CLEAN INTERIOR- NEW I PDI PRE-D
CAUSE: For the show
CORRECTION: Cleaned up unit for the show took about
30 minutes
1 COMPLAINT: VENT DUCTING WARRANTY REPAIR W 1021 FORES
CAUSE: Mfg did not install the vent to the
outlet
CORRECTION: Cut hole in paneling then installed the
vent and then attached the tubing to
back of vent
WARR COMPLAINT: WARRANTY REPAIR 2 - lots of debris W 1021 FORES
throughout unit from mfg metal shavings
that can damage flooring
CAUSE: Mfg
CORRECTION: Vacuumed up all debris under cabinets
slideroom etc REQUESTING .6
WARR COMPLAINT: WARRANTY REPAIR 5 - the exterior refer W 1021 FORES
does not work power at the outlet
confirmed
CAUSE: Not working diagnose after show
CORRECTION: NOTING
WARR COMPLAINT: WARRANTY REPAIR 6 - leak at connection W 1021 FORES
behind toilet
CAUSE: The connection in back of toilet is
loose

Continued on page 2

Work Order : 11694

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
CORRECTION: I tightened connection and no longer is
              dripping REQUESTING .1
WS      COMPLAINT:  WINTERIZE WATER SYSTEM & TRAPS -SELF      I      PDI      PRE-D
              CONTAINED - TOWABLE
CAUSE:      New unit
CORRECTION: Done

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
CIN      019079236326 TOILET TISSUE, SGL. 2 PL I-PDI      0      1.02      0.00
CIN      014717396042 HTS STANDARD 10' SEWER H I-PDI      0      7.46      0.00
CIN      019079900142 PARK ADAPTER BULK 30-15 I-PDI      0      4.34      0.00
WS      071247312003 -50 ANTIFREEZE/ 1 GALLON I-PDI      0      7.55      0.00

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
NTTS RV1F-1A NEW STOCK PREP HOD I-PDI 1.67 70.00 116.90
NTTS RV1F-1A NEW STOCK PREP HOD I-PDI 2.27 70.00 158.90
NTTS RV1F-1A NEW STOCK PREP HOD I-PDI 0.56 70.00 39.20
CIN CI CLEAN INTERIOR HOD I-PDI 0.10 70.00 7.00
1 WARR WARRANTY REPAIR HOD W-1021 0.50 115.00 57.50
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.41 115.00 47.15
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.09 115.00 10.35
ARR05 Z992 MISC LABOUR CODE (WARR W-1021 0.00 115.00 0.00
ARR05 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.01 115.00 1.15
ARR05 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.00 115.00 0.00
ARR06 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 115.00 57.50
WS W495 WINTERIZE RV (WATER SY HOD I-PDI 0.70 70.00 49.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I      PDI      0.00      371.00      0.00      0.00      0.00      371.00
W      1021      0.00      173.65      0.00      0.00      0.00      173.65

Totals      0.00      544.65      0.00      0.00      0.00      544.65

```

&k2S
&k0S