

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2255169
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	5ZT2PUTB7S4023102
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	425 / 425
Labor rate:	\$140.00	ITEM #	PUT283BHCE-1
OWNER INFORMATION		DEALER RO #	11694
ARRON BROCK		CLAIM START DATE	04/07/2025
120 BUFFALO ST		CLAIM END DATE	04/07/2025
Wisconsin Rapids, WI 54494			
USA			
Retail Date of Purchase	03/19/2025	WARRANTY EXPIRATION DATE	03/19/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-92-01-00-001194	Interior Wooden Vent Cover - Interior/Interior Miscellaneous/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2025-04-07 10:13:16 :: Complaint: Vent ducting. Vent under the bottom bunk is not attached to anything. Cause: Manufacturer did not install vent to the outlet. Correction: The tech used a hole saw to cut out a hole for a round vent then attached a round vent from parts to the front of the panel and used 2 screws to attached hose to back of the bent and then used aluminum tape to secure more.			
	Additional Note : greeneway@dealer-advisors.com, 2025-04-07 10:14:16 :: Unsure on labor code. No photos available as tech did the work already.			
Model#		Dlr Sub Hrs	0.50	Sub Labor Amt \$70.00
Serial#		Appr Hrs	0.00	Appr Labor Amt \$0.00
	Notes			
	no photos as required			

Labor

Line# 2	Operation Code	Operational Description		
	30-103-24-00-001125	Linoleum - Interior/Flooring/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2025-04-07 10:15:21 :: Complaint: There is a lot of debris throughout the unit from manufacturer, metal shavings that can damage the flooring. Cause: From manufacturing. Correction: Vacuumed up all debris under cabinets, slideroom, and throughout the unit.			
	Model#	Dlr Sub Hrs	0.60	Sub Labor Amt \$84.00
	Serial#	Appr Hrs	0.00	Appr Labor Amt \$0.00
	Notes			
	this is normal "shakedown" from transport of unit			

Labor

Line# 3	Operation Code	Operational Description		
	60-136-12-00-001500	Fitting - Plumbing/Fresh Water Supply/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2025-04-07 10:18:23 :: Complaint: Leak at the connection behind the toilet. Cause: The connection in the back of the toilet is loose. Correction: Tightened the connection and no longer leaking. Additional Note : greeneway@dealer-advisors.com, 2025-04-07 10:19:52 :: Only toilet repair code I could find was this. Unsure on correct labor code.			
	Model# 1	Dlr Sub Hrs	0.10	Sub Labor Amt \$14.00
	Serial# 1	Appr Hrs	0.10	Appr Labor Amt \$14.00
	Notes			

Submitted	Labor Amt	\$168.00
	Parts & Freight	\$0.00
	Total	\$168.00

Approved	Labor Amt	\$14.00
	Parts & Freight	\$0.00
	Total	\$14.00

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	