

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11696

Date In:	23 JAN 25	Author:	MGRAY
Promised Date:	04 JUL 25	Stock No:	11313
:	:	Year:	2025
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	FLAGSTAFF CLASSIC FW
:	WISCONSIN RAPIDS, WI	Model:	361RLS
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 6/6
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4FFLN27S1908134	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
NFWS    COMPLAINT:  NEW FIFTH WHEEL STOCK PREP                    I      PDI      PRE-D
        CAUSE:      STOCK PREP
        CORRECTION:  COMPLETE
WS       COMPLAINT:  WINTERIZE WATER SYSTEM & TRAPS -SELF        I      PDI      PRE-D
        CAUSE:      Unit needed to be winterized
        CORRECTION:  Unit winterized
WARR    COMPLAINT:  WARRANTY REPAIR 1 - PIECE OF TRIM CAM        W      1021     FORES
        CAUSE:      Trim fell off
        CORRECTION:  Re nailed trim back up
WARR    COMPLAINT:  WARRANTY REPAIR 2 - WINDOW IN BEDROOM        W      1021     FORES
        CAUSE:      HAS A BEND IN PART OF THE FRAME WHERE
        CORRECTION:  THE TWO WINDOWS MEET
        CAUSE:      NOTING FOR MFG
        CORRECTION:  NOTING
WARR    COMPLAINT:  WARRANTY REPAIR 3 - RUBBER STOPPER          W      1021     FORES
        CAUSE:      MISSING FROM STOVE FOR THE GRILL COVERS
        CORRECTION:  MFG
        CORRECTION:  PUT NEW RUBBER STOPPER IN
WARR    COMPLAINT:  WARRANTY REPAIR 4 - COAT RACK IN THE        W      1021     FORES
        CAUSE:      BEDROOM CLOSET IS BENT
        CORRECTION:  Coat rack was bent from mfg screws were
        CORRECTION:  over torqued
        CORRECTION:  Replaced with new coat rack
WARR    COMPLAINT:  WARRANTY REPAIR 5 - CHIP ON THE BACK        W      1021     FORES
        CAUSE:      SIDE OF THE ISLAND IN THE KITCHEN
        CORRECTION:  FROM MFG. NEED TO USE PUTTY TO FIX CHIP
*****
```

Continued on page 2

Work Order : 11696

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                IN ISLAND AND A PAINT PEN TO MATCH COLOR
CORRECTION: REQUESTING .50 FOR LABOR APPROVED
WARR COMPLAINT: WARRANTY REPAIR 6 - NOTING THAT THERE      W      1021    FORES
                                ARE SCRATCHES IN THE SINK
CAUSE:      MFG
WARR COMPLAINT: WARRANTY REPAIR 7 - THE WATER LINE      W      1021    FORES
                                CONNECTORS FOR THE WASHER IN THE BEDROOM
                                ARE LEAKING
CAUSE:      The hot side on water connection was
                                leaking when shut off
CORRECTION: Replaced with new part
WARR COMPLAINT: Transferred to GRV*11696B on 19 FEB 25  W      1021    FORES
                                Estimate amount was 0.00 WARRANTY REPAIR
                                8 - CONTROL BOARD FOR ALL OF THE
                                ELECTRICAL IS NOT FUNCTIONING PROPERLY
CAUSE:      THE PART IS FAULTY FROM MFG. NEED TO
                                REPLACE CONTROL BOARD
CORRECTION: REQUESTING 1 HOUR

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WS      071247312003 -50 ANTIFREEZE/ 1 GALLON I-PDI          3        7.55      22.65
WARR0 2022120244    COOKTOP GRATE GR2OMMET S W-1021          0        1.83        0.00
WARR0 822059801     CLOSET ROD -PFL:BLACK - W-1021          1        8.00        8.00

```

```

*****
Job# Lab Code Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
NFWS RV1F-1A NEW STOCK PREP          JT      I-PDI          0.56      70.00      39.20
NFWS RV1F-1A NEW STOCK PREP          JT      I-PDI          1.41      70.00      98.70
NFWS RV1F-1A NEW STOCK PREP          JT      I-PDI          2.53      70.00     177.10
NFWS RV1F-1A NEW STOCK PREP          JT      I-PDI          0.00      70.00        0.00
WS W495 WINTERIZE RV (WATER SY JT      I-PDI          0.70      70.00      49.00
ARR01 Z992 MISC LABOUR CODE (WARR JT      W-1021          0.50     115.00      57.50
ARR02 Z992 MISC LABOUR CODE (WARR JT      W-1021          0.00     115.00        0.00
ARR02 Z992 MISC LABOUR CODE (WARR JT      W-1021          0.04     115.00        4.60
ARR03 Z992 MISC LABOUR CODE (WARR JT      W-1021          0.00     115.00        0.00
ARR04 Z992 MISC LABOUR CODE (WARR JT      W-1021          0.50     115.00      57.50
ARR05 Z992 MISC LABOUR CODE (WARR JT      W-1021          0.00     115.00        0.00
ARR06 Z992 MISC LABOUR CODE (WARR JT      W-1021          0.00     115.00        0.00
ARR07 Z992 MISC LABOUR CODE (WARR JT      W-1021          0.50     115.00      57.50
ARR08 Z992 MISC LABOUR CODE (WARR JT      W-1021          0.00     115.00        0.00

```

```

*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR03 FRT      FREIGHT FOR JOB 3      W-1021          1.00     12.47      12.47
ARR04 FRT      FREIGHT      W-1021          1.00     18.31      18.31

```

Continued on page 3

Work Order : 11696

```

*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
ARR07  M        MISCELLANEOUS PN:4809281 A W-1021    0.00    0.00    0.00
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id          Parts    Labour    Sublet    Extras      Tax      Total
*****
I    PDI              22.65    364.00     0.00     0.00     0.00    386.65
W    1021              8.00    177.10     0.00    30.78     0.00    215.88

      Totals          30.65    541.10     0.00    30.78     0.00    602.53

```

&k2S
&k0S