

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 11696

|                 |                        |                 |                      |
|-----------------|------------------------|-----------------|----------------------|
| Date In:        | 23 JAN 25              | Author:         | MGRAY                |
| Promised Date:  | 04 JUL 25              | Stock No:       | 11313                |
| :               | :                      | Year:           | 2025                 |
| Customer Name:  | 1000 - GREENEWAY RV SA | Manufacturer:   | FOREST RIVER         |
| Address:        | 8220 STATE HWY 13 SOUT | Brand:          | FLAGSTAFF CLASSIC FW |
| :               | WISCONSIN RAPIDS, WI   | Model:          | 361RLS               |
| Postal/Zip:     | 54494                  | Miles/Hrs:      | 0                    |
| Phone#(res):    | 800-758-2272           | Exterior Color: |                      |
| Phone#(bus):    |                        | Unit Type:      | FW-FIFTH WHEEL       |
| Cell Phone:     |                        | License#:       |                      |
| Email:          | NONE                   | Tag#:           |                      |
| Purchased Date: |                        | :               |                      |
| Delivery Date:  |                        | :               |                      |
| InService Date: |                        | :               |                      |
| Serial#:        | 4X4FFLN27S1908134      | :               |                      |

\*\*\*\*\*

| Job # | Description                                                                                                                                                                                                          | JOB INFORMATION | Type | Bill To    |
|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|------|------------|
| CEN   | CLEAN EXTERIOR- NEW                                                                                                                                                                                                  |                 | I    | PDI PRE-D  |
| NFWS  | NEW FIFTH WHEEL STOCK PREP                                                                                                                                                                                           |                 | I    | PDI PRE-D  |
| WS    | WINTERIZE WATER SYSTEM & TRAPS -SELF CONTAINED - TOWABLE                                                                                                                                                             |                 | I    | PDI PRE-D  |
| WARR  | COMPLAINT: WARRANTY REPAIR 1 - PIECE OF TRIM CAM OFF LEFT FRONT SIDE OF THE BED.<br>CAUSE: WILL NEED TO RENAIL THE PIECE OF TRIM BACK ONTO THE BED<br>CORRECTION: REQUESTING .30 FOR LABOR                           |                 | W    | 1021 FORES |
| WARR  | COMPLAINT: WARRANTY REPAIR 2 - WINDOW IN BEDROOM HAS A BEND IN PART OF THE FRAME WHERE THE TWO WINDOWS MEET<br>CAUSE: NOTING FOR MFG                                                                                 |                 | W    | 1021 FORES |
| WARR  | COMPLAINT: WARRANTY REPAIR 3 - RUBBER STOPPER MISSING FROM STOVE FOR THE GRILL COVERS<br>CAUSE: MFG<br>CORRECTION: PUT NEW RUBBER STOPPER IN                                                                         |                 | W    | 1021 FORES |
| WARR  | COMPLAINT: WARRANTY REPAIR 4 - COAT RACK IN THE BEDROOM CLOSET IS BENT<br>CAUSE: NEED TO TRY AND BEND BACK INTO PLACE OR REPLACE COAT RACK<br>CORRECTION: REQUESTING .50 FOR LABOR                                   |                 | W    | 1021 FORES |
| WARR  | COMPLAINT: WARRANTY REPAIR 5 - CHIP ON THE BACK SIDE OF THE ISLAND IN THE KITCHEN<br>CAUSE: FROM MFG. NEED TO USE PUTTY TO FIX CHIP IN ISLAND AND A PAINT PEN TO MATCH COLOR<br>CORRECTION: REQUESTING .50 FOR LABOR |                 | W    | 1021 FORES |
| WARR  | COMPLAINT: WARRANTY REPAIR 6 - NOTING THAT THERE                                                                                                                                                                     |                 | W    | 1021 FORES |

Continued on page 2

Work Order : 11696

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
                ARE SCRATCHES IN THE SINK
CAUSE:      MFG
WARR        COMPLAINT:      WARRANTY REPAIR 7 - THE WATER LINE      W      1021      FORES
                CONNECTORS FOR THE WASHER IN THE BEDROOM
                ARE LEAKING
CAUSE:      BAD CONNECTOR FOR THE WASHER LINE WHICH
                WAS CAUSING TE LEAK. NEED TO REPLACE
CORRECTION: REQUESTING 1 HOUR LABOR

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WS      071247312003 -50 ANTIFREEZE/ 1 GALLON I-PDI      0      7.55      0.00

```

```

*****
Job# Lab Code      Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
CEN CE      CLEAN EXTERIOR      I-PDI      0.00      70.00      0.00
NWFS RV1F-1A NEW STOCK PREP      I-PDI      0.00      70.00      0.00
WS W495      WINTERIZE RV (WATER SY      I-PDI      0.00      70.00      0.00
ARR01 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00
ARR03 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00
ARR04 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00
ARR05 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00
ARR06 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00
ARR07 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00

```

```

*****
                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
Totals      0.00      0.00      0.00      0.00      0.00      0.00

```

&k2S  
&k0S