

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11697

Date In: 23 JAN 25 Author: MGRAY
Promised Date: 04 JUL 25 Stock No: 11278
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT Brand: TRANSCEND XPLORE
: WISCONSIN RAPIDS, WI Model: 26BHX
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#:
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573TT3121S8836242 :

Job # Description JOB INFORMATION Type Bill To

CEN COMPLAINT: CLEAN EXTERIOR- NEW I PDI PRE-D
CAUSE: Camper needs wash and de salt
CORRECTION: De salted camper and washed camper
NTTS COMPLAINT: NEW TRAVEL TRAILER STOCK PREP I PDI PRE-D
CAUSE: New stock prep
CORRECTION: New stock prep complete
WS COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF I PDI PRE-D
CONTAINED - TOWABLE
CAUSE: Need winterize after prep
CORRECTION: Drained hot water heater put in bypass
and winterize with 3 gallons of
antifreeze
WARR COMPLAINT: NOTICED DURING PREP THAT THE SCREWS HAD W 1020 GRAND
BROKE OFF THE QUICK DISCONNECT
CAUSE: The screws that hold the quick
disconnect to the frame snapped off
CORRECTION: Removed the broke off screws that were
still in the frame and reattached with
new screws REQUESTING .70 HOURS
WARR COMPLAINT: Silicone around blub seals is bubbled W 1020 GRAND
and missing Silicone and has holes in it
CAUSE: Bulb seal around sildeout was fully
sealed from factory had holes in the
silicone
CORRECTION: Resealed around bulb seal with clear
silicone to cover up holes so now is
completely sealed REQUESTING .50 HOURS
WARR COMPLAINT: NOTICED DURING PREP THAT THERE WERE W 1020 GRAND

Continued on page 2

Work Order : 11697

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
              STAPLES POKING THROUGH IN THE KITCHEN
              CABINET
      CAUSE:      Staple popping up in cabinet
      CORRECTION: Removed staple and filled in with putty
              REQUESTING .50 HOURS
WARR      COMPLAINT: Underbelly has gap in were gas line is      W      1020      GRAND
      CAUSE:      Lp line and underbelly hanging down and
              has gaps
      CORRECTION: Just needed one more lp clamp and a self
              tapping screw all sealed up now
              REQUESTING .30 HOURS

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WS      071247312003 -50 ANTIFREEZE/ 1 GALLON I-PDI      0      7.55      0.00

```

```

*****
Job# Lab Code      Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
      CEN CE      CLEAN EXTERIOR      CF      I-PDI      0.00      70.00      0.00
      NTTS RV1F-1A NEW STOCK PREP      CF      I-PDI      0.10      70.00      7.00
      WS W495      WINTERIZE RV (WATER SY CF      I-PDI      0.70      70.00      49.00
      CEN CE      CLEAN EXTERIOR      CF      I-PDI      0.10      70.00      7.00
      NTTS RV1F-1A NEW STOCK PREP      CF      I-PDI      1.00      70.00      70.00
      NTTS RV1F-1A NEW STOCK PREP      CF      I-PDI      2.02      70.00      141.40
      NTTS RV1F-1A NEW STOCK PREP      CF      I-PDI      0.30      70.00      21.00
      NTTS RV1F-1A NEW STOCK PREP      CF      I-PDI      0.26      70.00      18.20
ARR01 Z992      MISC LABOUR CODE (WARR CF      W-1020      0.50      115.00      57.50
ARR02 Z992      MISC LABOUR CODE (WARR CF      W-1020      0.50      115.00      57.50
      NTTS RV1F-1A NEW STOCK PREP      CF      I-PDI      0.07      70.00      4.90
      NTTS RV1F-1A NEW STOCK PREP      CF      I-PDI      0.48      70.00      33.60
ARR04 Z992      MISC LABOUR CODE (WARR CF      W-1020      0.50      115.00      57.50
ARR05 Z992      MISC LABOUR CODE (WARR CF      W-1020      0.50      115.00      57.50
      NTTS RV1F-1A NEW STOCK PREP      CF      I-PDI      0.26      70.00      18.20
      NTTS RV1F-1A NEW STOCK PREP      CF      I-PDI      0.01      70.00      0.70

```

```

*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01 SSE      SHOP SUPPLIES - EXTERNAL      W-1020      1.00      0.00      0.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I      PDI      0.00      371.00      0.00      0.00      0.00      371.00
W      1020      0.00      230.00      0.00      0.00      0.00      230.00

```

Continued on page 3

Work Order : 11697

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	0.00	601.00	0.00	0.00	0.00	601.00

&k2S
&k0S