

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 11699

Date In: 27 JAN 25 Author: KOTT
 Promised Date: 25 DEC 24 Stock No: 11314
 : Year: 2025
 Customer Name: 17577 - MONTEVERDE, JA Manufacturer: FOREST RIVER
 Address: 2095 ELO RD Brand: CEDAR CREEK COTTAGE
 : PICKETT, WI Model: 40CBK
 Postal/Zip: 54964 Miles/Hrs: 0
 Phone#(res): 920-267-1228 Exterior Color:
 Phone#(bus): Unit Type: TT-TRAVEL TRAILER
 Cell Phone: License#:
 Email: JACLYN.FISHER@HOTMAIL. Tag#: UNIT ARRIVED 2/17
 Purchased Date: 25 JAN 25 :
 Delivery Date: 25 DEC 24 :
 InService Date: :
 Serial#: 4X4TCRS25SS234451 :

Job #	Description	JOB INFORMATION	Type	Bill To
1	VISTA ROYAL CAMPGROUND BANCORFT, WI 54921 SITE 256		I	DO DEALE
2	ATTACH "A" FRAME TO CEDAR CREEK WHEN PICKING UP		I	DO DEALE
	TRADE IN- TAKE 6 BOLTS WITH YOU TO ATTACH-			
3	HITCH CREDIT		I	DO DEALE
ZB8	ZONE B- 8 PT BLOCK		I	DO DEALE
ST	SHOWTHRU&SHOWOUT SALESMAN: DAKOTA		I	PDI PRE-D
CIN	CLEAN INTERIOR- NEW		I	PDI PRE-D
CEN	CLEAN EXTERIOR- NEW		I	PDI PRE-D
SCP	SOLD COMPLETE PREP		I	PDI PRE-D
DAF	DAF-WARRANTY REPAIRS- 1. FRONT BEDROOM BLIND DOESN'T I		I	PDI PRE-D
	OPPERATE 2.PANELLING MISSING IN BEDROOM CLOSET			
	3.SAMLL HOLES IN DINING ROOM TABLE 4.SMALL HOLES IN			
	BAR EXTENDER ON ISLAND 5.PEELING PANELLING IN DINETE			
	6. SCUFFS ON PANTRY DOOR 7. SEAM TAPE BUBBLING IN			
	BATHROOM 8. SEAM TAPE BUBBLING BY COUCH 9. LARGE GAP			
	IN BATHROOM CABINET 10. SMALL CRACK IN WINDOW OF			
	BEDROOM 11. SCUFFED FLOOR BY COUCH 12.LOFT WINDOW			
	BLOW OUT 13. SCUFFS ON SIDEWALL BY LOFT 14. GUTTER			
	TRACK DAMAGED FROM WINDOW BLOW OUT 15. BATON STRIP			
	HANGING IN KITCHEN			
WARR	COMPLAINT: WARRANTY REPAIR 1 - THE BLIND ELECTRIC		W	1021 FORES
	BLIND IN THE BAY WINDOW OF THE BEDROOM			
	SKIPS WHILE OPERATING			
	CAUSE: Daf			
	CORRECTION: I found nothing wrong with the blinds			
	operation it did get hung up for a			
	second at the bottom then extended and			
	worked as it should			

Continued on page 2

Work Order : 11699

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 2 - THERE IS NO           W    1021   FORES
        PANELLING ON THE UPPER PART OF THE INNER
        CLOSET AND THE WOOD IS CRACKED
        CAUSE:      Mfg
        CORRECTION: This should be ok it's on the inside of
        the closet
WARR    COMPLAINT:  WARRANTY REPAIR 3 - TINY HOLES           W    1021   FORES
        THROUGHOUT THE WHOLE OF THE DINING ROOM
        TABLE
        CAUSE:      Mfg it is part of the decor
        CORRECTION: Nothing to be done part of the decor
WARR    COMPLAINT:  WARRANTY REPAIR 4 - TINY HOLES           W    1021   FORES
        THROUGHOUT THE BAR EXTENDER ON THE
        KITCHEN ISLAND
        CAUSE:      Mfg decor
        CORRECTION: Part of the decor nothing to be done
WARR    COMPLAINT:  WARRANTY REPAIR 5 - PANELING BY THE           W    1021   FORES
        DINETE IS STARTING TO PEEL UP TOWARDS
        THE BOTTOM OF THE WALL
        CAUSE:      Panel bowed outward a bit
        CORRECTION: I used a chunk of wood and tapped it
        back with a hammer so panel is not
        sticking outward I then pressed the
        finish (paper) on wall board down
        REQUESTING .20 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 6 - THERE ARE SCUFF           W    1021   FORES
        MARKS ALL DOWN THE SIDE OF THE PANTRY
        DOOR
        CAUSE:      Mfg
        CORRECTION: Filled with putty REQUESTING .20 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 7 - SEAM TAPE BEHIND THE W    1021   FORES
        COUCH IS STARTING TO BUBBLE
        CAUSE:      Loose tape
        CORRECTION: Pressed into place REQUESTING .05 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 8 - SEAM TAPE ON THE           W    1021   FORES
        CEILING OF THE BATHROOM IS STARTING TO
        BUBBLE
        CAUSE:      Bubbled loose seam tape
        CORRECTION: I was able to press the tape back down
        into place REQUESTING .05 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 9 - THERE IS A LARGE GAP W    1021   FORES
        AT THE BOTTOM OF THE CABINET ON THE DS
        OF THE SINKS IN THE BATHROOM
        CAUSE:      Slight bow towards top of the cab door
        CORRECTION: There is a larger gap at the top but the
        door latches as it should and stays
        closed wait on this to see if customer
        has a issue with this or not
WARR    COMPLAINT:  WARRANTY REPAIR 10 - SMALL CRACK IN THE W    1021   FORES

```

Continued on page 3

Work Order : 11699

	CAUSE:	BAY WINDOW OF THE BEDROOM LOOKS LIKE SOMETHING HIT THE WINDOW CAUSING IT TO CRACK			
	CORRECTION:	SUBLET NEED ESTIMATE			
WARR	COMPLAINT:	WARRANTY REPAIR 11 - THERE ARE SCUFFS IN W THE FLOOR FROM THE WHEELS OF THE COUCH WHEN THE SLIDE OUT IS PULLED IN/OUT	1021		FORES
	CAUSE:	The way it is made			
	CORRECTION:	Once floor is wiped up you no longer see scuffs and the wheels no longer have dirt on them to cause it to look dirty			
WARR	COMPLAINT:	WARRANTY REPAIR 12 - WINDOW ON THE DS OF W THE FRONT LOFT BLEW OFF	1021		FORES
	CAUSE:	WINDOW WAS NOT LATCHED PROPERLY AND BLEW OFF THE UNIT CAUSING DAMAGE TO THE SCREW TRACK AND SCUFFS ON THE SIDE WALL			
	CORRECTION:	REQUESTING 1.50 HOURS			
WARR	COMPLAINT:	WARRANTY REPAIR 13 - DS UPPER SIDE WALL W BY LOFT WINDOW SCUFFED	1021		FORES
	CAUSE:	SCUFFED FROM WINDOW BLOWING OUT AND BOUNCING OFF SIDE WALL. NEED TO BUFF			
	CORRECTION:	REQUESTING 3 HOURS			
WARR	COMPLAINT:	WARRANTY REPAIR 14 - SOME SEAM TAPE IN W THE CABINET BY THE SHOWER IS COMING UP AND THERE ARE VERY OBVIOUS NAIL MARKS IN THE PANELING	1021		FORES
	CAUSE:	Loose trim and nail holes			
	CORRECTION:	Pressed tape into place then filled holes with putty REQUESTING .30 HOURS			
WARR	COMPLAINT:	WARRANTY REPAIR 15 - GUTTER RAIL HAD W BEEN HIT AND DAMAGED WHEN THE WINDOW HAD BLEW OUT OF THE FRAME	1021		FORES
	CAUSE:	THE WINDOW THAT BLEW OUT ENDED UP SPINNING WHILE CAUGHT ON PART OF THE FRAME AND CAUSED DAMAGE TO THE GUTTER RAIL			
	CORRECTION:	need to replace an 8ft section REQUESTING 1.60 HOURS			
WARR	COMPLAINT:	WARRANTY REPAIR 16- BATON STRIP IN W KITCHEN NEAR THE CEILING FAN IS FALLING OFF JUST A LITTLE BIT	1021		FORES
	CAUSE:	Loose plastic ceiling trim			
	CORRECTION:	I used gel crazy glue and put in the ceiling panel gap then pressed and taped the plastic ceiling trim into place will remove tape tomorrow when glue is dry and trim is secured REQUESTING .20 HOURS			
WARR	COMPLAINT:	WARRANTY REPAIR 17 the mirror in W bathroom ds above sinks mirror has a deep scratch near the bottom	1021		FORES
	CAUSE:	Mfg it's nearly impossible to get a good pic of the scratch it's the best I could			

Continued on page 4

Work Order : 11699

get . Please order new mirror or can door with mirror 20 1/2"w x 29" long

WARR CORRECTION: REQUESTING .30 HOURS
 COMPLAINT: WARRANTY REPAIR 18 step going down to W 1021 FORES
 bedroom and steps going up into the loft have a few good deep gouges and scratches
 CAUSE: Scratched
 CORRECTION: I used wood paint pen to cover the scratches on the step to bedroom and the steps to the loft REQUESTING .30 HOURS

WARR COMPLAINT: WARRANTY REPAIR 19- THE MIRROR IN THE E 17577 MONTE
 BATHROOM HAS A GAP BETWEEN THE CABIET AND THE BOTTOM TRIM.
 CAUSE: IT LOOKS AS IF THE CABINET FOR THE MIRRORS IS SMALLER THAN THE BOTTOM PORTION OF THE CABINET. NEED TO FILL IN WITH BROWN SILICONE
 CORRECTION: REQUESTING .50 HOURS

WS WINTERIZE WATER SYSTEM & TRAPS -SELF CONTAINED - E 17577 MONTE
 TOWABLE

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
ZB8	081628593006	FOUNDATION PAD 16" X 18"	I-DO		0	7.98	0.00
ZB8	51700202	BLOCK 8" REGULAR 8"	I-DO		0	4.04	0.00
ZB8	113997	HARDWOOD WEDGE 5.5"X10.5	I-DO		0	2.24	0.00
CIN	019079236326	TOILET TISSUE, SGL. 2 PL	I-PDI		1	1.02	1.02
CIN	014717396042	HTS STANDARD 10' SEWER H	I-PDI		1	7.46	7.46
CIN	019079900142	PARK ADAPTER BULK 30-15	I-PDI		1	4.34	4.34
SCP	840821034507	12V 24 MDP BATTERY	I-PDI		0	85.20	0.00
CIN	093344312410	ADAPTER 30 AMP MALE TO 5	I-PDI		1	24.55	24.55
WS	071247312003	-50 ANTIFREEZE/ 1 GALLON	E-17577		0	10.69	0.00
WARR1	82209996	COTTAGE GLASS / FRONT CA	W-1021		0	567.46	0.00
WARR1	82203948	WINDOW 36"X22" EXIT, FRA	W-1021		0	92.20	0.00

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
ZB8	DEL	DELIVERY- ZONE B- 8PT			I-DO	0.00	70.00	0.00
	ST RV1D-3	SHOW THRU & PICK UP PD			I-PDI	0.00	70.00	0.00
CIN	CI	CLEAN INTERIOR			I-PDI	0.00	70.00	0.00
CEN	CE	CLEAN EXTERIOR		CF	I-PDI	0.00	70.00	0.00
	2 Z991	MISC CODE (NTERNAL)			I-DO	0.00	70.00	0.00
SCP	RV1F-3	SOLD COMPLETE PREP	HOD		I-PDI	0.89	70.00	62.30
DAF	Z991	DAF-WARRANTY REPAIR	HOD		I-PDI	0.10	70.00	7.00
ARR01	Z992	MISC LABOUR CODE (WARR HOD			W-1021	0.50	115.00	57.50
ARR02	Z992	MISC LABOUR CODE (WARR HOD			W-1021	0.50	115.00	57.50
ARR03	Z992	MISC LABOUR CODE (WARR HOD			W-1021	0.50	115.00	57.50
ARR04	Z992	MISC LABOUR CODE (WARR HOD			W-1021	0.50	115.00	57.50
ARR05	Z992	MISC LABOUR CODE (WARR HOD			W-1021	0.50	115.00	57.50

Continued on page 5

Work Order : 11699

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   115.00   57.50
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   115.00   57.50
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   115.00   57.50
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   115.00   57.50
ARR10 Z992      MISC LABOUR CODE (WARR      W-1021    0.00   115.00    0.00
ARR11 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   115.00   57.50
ARR12 Z992      MISC LABOUR CODE (WARR      W-1021    0.00   115.00    0.00
ARR13 Z992      MISC LABOUR CODE (WARR      W-1021    0.00   115.00    0.00
ARR14 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.49   115.00   56.35
ARR15 Z992      MISC LABOUR CODE (WARR      W-1021    0.00   115.00    0.00
ARR16 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   115.00   57.50
  CEN CE      CLEAN EXTERIOR      CF  I-PDI    1.30    70.00   91.00
ARR17 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.20   115.00   23.00
  SCP RV1F-3  SOLD COMPLETE PREP  HOD  I-PDI    0.70    70.00   49.00
ARR17 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.30   115.00   34.50
  SCP RV1F-3  SOLD COMPLETE PREP  HOD  I-PDI    1.42    70.00   99.40
ARR18 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   115.00   57.50
ARR19 Z992      MISC LABOUR CODE (WARR HOD E-17577  0.50   140.00   70.00
  WS W495     WINTERIZE RV (WATER SY HOD E-17577  0.70   140.00   98.00
  SCP RV1F-3  SOLD COMPLETE PREP  HOD  I-PDI    1.04    70.00   72.80
ARR14 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.01   115.00    1.15
  SCP RV1F-3  SOLD COMPLETE PREP  HOD  I-PDI    0.45    70.00   31.50
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
  3  M      HITCH TRADE      I-DO    0.00  0.00  0.00
  SCP LP    PROPANE      I-PDI    0.00  0.00  0.00
ARR17 SSE  SHOP SUPPLIES - EXTERNAL  W-1021  1.00  12.60  12.60
*****
```

CUSTOMER COMMENTS

THIS WILL BE REQUESTING 2 HOURS FOR REPAIR

BILLINGS SUMMARY

```
*****
Type Bill Id    Parts    Labour    Sublet    Extras    Tax    Total
*****
E  17577        0.00    168.00    0.00    0.00    9.24    177.24
I  PDI        37.37    413.00    0.00    0.00    0.00    450.37
W  1021        0.00    805.00    0.00    12.60    0.00    817.60

Totals        37.37   1386.00    0.00    12.60    9.24    1,445.21
*****
```

&k2S
&k0S