

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497  
 GREENEWAY INC  
 DBA GREENEWAY RV SALES & SERVICE  
 8220 STATE HWY 13 SOUTH  
 WISCONSIN RAPIDS, WI 54494  
 USA

CLAIM STATUS Paid  
 CLAIM 2254051  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4TPUS2XSP104353  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 420 / 420  
 ITEM # PUT402LFT  
 DEALER RO # 11707B  
 CLAIM START DATE 04/04/2025  
 CLAIM END DATE 04/07/2025

Labor rate: \$140.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 1**      **Operation Code**      **Operational Description**  
 20-46-24-00-000721      Window - Exterior/Windows/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-04-04 13:12:47 :: Complaint: Most windows have clear silicone smeared on them. Cause: Manufacturer had silicone smeared all over the windows. Correction: Used quick solve and removed silicone from inside windows and exterior windows.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	1.00	<b>Sub Labor Amt</b> \$140.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.50	<b>Appr Labor Amt</b> \$70.00

**Notes**  
 wash date?  
  
 nothing noted on DAF dated 11/24  
 Wash date was 04/02/2025  
 dealer goodwill  
  
 nothing noted on DAF

### Labor

**Line# 2**      **Operation Code**      **Operational Description**  
 30-103-04-00-001119      Carpet - Interior/Flooring/Clean/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-04-04 13:14:41 :: Complaint: Silicone in carpeting. Cause: Manufacturing defect. Correction: Used quick solve to remove the silicone in carpeting.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.50	<b>Sub Labor Amt</b> \$70.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b> \$42.00

**Notes**  
 spot clean  
  
 nothing noted on DAF

### Labor

**Line# 3**      **Operation Code**      **Operational Description**  
 30-102-24-00-004562      Gimp/Vinyl Trim - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-04-04 13:15:52 :: Complaint: Parts of trim not finished from manufacturer. Cause: Manufacturer left unfinished. Correction: Filled with putty then used wood paint to blend.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b> \$28.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b> \$28.00

**Notes**

**Labor**

Line# 4

**Operation Code**

30-102-24-00-004562

**Operational Description**

Gimp/Vinyl Trim - Interior/Panels, Ceilings, &amp; Interior Moldings/Repair/No Tread Code

**Complaint, Cause, Correction**

Original Note : greeneway@dealer-advisors.com, 2025-04-04 13:18:40 :: Complaint: Holes in trim from manufacturer. Cause: Manufacturing defect. Correction: Used putty to fill the holes.

**Model#****Dlr Sub Hrs**

0.10

**Sub Labor Amt** \$14.00**Serial#****Appr Hrs**

0.10

**Appr Labor Amt** \$14.00**Notes****Submitted**

Labor Amt	\$252.00
Parts & Freight	\$0.00
Total	\$252.00

**Approved**

Labor Amt	\$154.00
Parts & Freight	\$0.00
Total	\$154.00

**DEALER****DATE****SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

**CUSTOMER****DATE****SIGNATURE**

All repairs described have been inspected and are satisfactory.