

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11707C

Date In:	12 MAY 25	Author:	DLUCAS
Promised Date:	20 JUN 25	Stock No:	11258
:	:	Year:	2025
Customer Name:	17595 - BIRSCHBACH, TH	Manufacturer:	FOREST RIVER
Address:	4290 STONEGATE DR	Brand:	PUMA DESTINATION
:	OSHKOSH, WI	Model:	402LFT
Postal/Zip:	54904	Miles/Hrs:	0
Phone#(res):	9205391547	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	TBIRSCH54@GMAIL.COM	Tag#:	5/19
Purchased Date:	17 JAN 25	:	:
Delivery Date:	25 APR 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS2XSP104353	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 5 - THERE IS A LEAK          W    1021    FORES
          UNDER THE SINK WHEN USING THE "BAR
          FAUCET" - CMR WILL SHOW YOU AT SITE.
CAUSE:   pics taken what I diagnose is the veggie
          sprayer is cracked allowing water to
          drain into lower sink cabinet
CORRECTION: removed and install new veggie sprayer I
          couldn't test due to water supply locked
          up
SC      SERVICE CALL: 1023 CARDIFF COURT- ROME                  E    17595    BIRSC
1      COMPLAINT:  CUSTOMER STATES THAT ONE OF THE CLIPS ON W    1021    FORES
          THE BATHROOM MIRROR IS BROKEN-
CAUSE:   Will need plastic mirror clips pics
          taken
CORRECTION: remove and install the new plastic clip
          that holds mirror to wall
2      COMPLAINT:  CUSTOMER STATES THAT THE STOPPER AT THE W    1021    FORES
          BOTTOM OF THE SINK IN THE KITCHEN THAT
          IS SUPPOSED TO HOLD WATER DOES NOT HOLD
          ANY WATER-
CAUSE:   the drainer stopper does work insert the
          stopper in sink drain and then turn
          stainless dial to left to lock into
          place for tight seal. NEED .10 FOR
          REPAIR.
CORRECTION: put strainer into place for kitchen sink
          and then turn stainless dial to left to
          lock in
```

Continued on page 2

Work Order : 11707C

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
3      COMPLAINT:  CUSTOMER STATES THAT THE SCREEN DOOR        W    1021    FORES
                DOES NOT GO INTO THE TRACK- IT IS BY THE
                KITCHEN SINK-
                CAUSE:    we need to get ahold mfg about these
                        screen door are not right corners of
                        screen door digging in metal I tried
                        adjusting the wheels seems like they
                        angled the wrong directions does not
                        work with patio frame is there a
                        different option screen door we can try
                        I've come across several like this they
                        don't work I've tried flipping screen
                        door still not right
                CORRECTION: still the same screen door design I
                        installed and adjustments done the best
                        I can to make it work
*****

```

```

*****
Job # Part No   Description      PARTS      Bill to   Qty   Price   Total
*****
WARR0 822069730 SINK PART: BLACK SINK SPRA W-1021      1    17.16   17.16
1      822091598 CLIP, MIRROR CLEAR PLASTIC W-1021      1     0.07    0.07
3      822053515A SCREEN DOOR FOR PATIO DOOR W-1021      1    53.13   53.13
*****

```

```

*****
Job# Lab Code Description    LABOUR    Mech Bill to   Hrs   Rate   Total
*****
ARR05 Z992      MISC LABOUR CODE (WARR JS   W-1021    0.52  140.00   72.80
ARR05 WARR      MANUFACTURER WARRANTY JS   W-1021    0.50  140.00   70.00
1 WARR      MANUFACTURER WARRANTY JS   W-1021    0.50  140.00   70.00
1 WARR      MANUFACTURER WARRANTY JS   W-1021    0.50  140.00   70.00
2 WARR      MANUFACTURER WARRANTY JS   W-1021    0.25  140.00   35.00
3 WARR      MANUFACTURER WARRANTY JS   W-1021    0.65  140.00   91.00
3 WARR      MANUFACTURER WARRANTY JS   W-1021    0.10  140.00   14.00
*****

```

```

*****
Job # Excode   Description    EXTRAS      bill to   Qty   Price   Total
*****
SC SSE      SHOP SUPPLIES - EXTERNAL E-17595    1.00    0.00    0.00
SC SC       SERVICE CALL           E-17595   15.00    3.75   56.25
SC SC       SERVICE CALL           E-17595   15.00    3.75   56.25
3 FRT       FREIGHT FOR DOOR, CLIP AND W-1021    1.00  161.04  161.04
*****

```

```

*****
Type Bill Id   Parts   Labour   Sublet   Extras   Tax   Total
*****
E   17595      0.00    0.00    0.00    112.50   6.22   118.72
W   1021      70.36   422.80    0.00    161.04   0.00   654.20
*****

```

Continued on page 3

Work Order : 11707C

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	70.36	422.80	0.00	273.54	6.22	772.92

&k2S
&k0S