

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11707C

Date In:	12 MAY 25	Author:	KOTT
Promised Date:	19 MAY 25	Stock No:	11258
:	:	Year:	2025
Customer Name:	17595 - BIRSCHBACH, TH	Manufacturer:	FOREST RIVER
Address:	4290 STONEGATE DR	Brand:	PUMA DESTINATION
:	OSHKOSH, WI	Model:	402LFT
Postal/Zip:	54904	Miles/Hrs:	0
Phone#(res):	9205391547	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	TBIRSCH54@GMAIL.COM	Tag#:	5/19
Purchased Date:	17 JAN 25	:	:
Delivery Date:	25 APR 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS2XSP104353	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 5 - THERE IS A LEAK          W    1021    FORES
          UNDER THE SINK WHEN USING THE "BAR
          FAUCET" - CMR WILL SHOW YOU AT SITE.
CAUSE:    pics taken what I diagnose is the veggie
          sprayer is cracked allowing water to
          drain into lower sink cabinet
CORRECTION: Will need a new veggie sprayer ....
          REQUESTING .5 FOR VEGGIE SPRAYER REMOVE
          AND REPLACE

SC      SERVICE CALL: 1023 CARDIFF COURT- ROME                  E    17595    BIRSC
1        COMPLAINT:  CUSTOMER STATES THAT ONE OF THE CLIPS ON W    1021    FORES
          THE BATHROOM MIRROR IS BROKEN-
CAUSE:    Will need plastic mirror clips pics
          taken
CORRECTION: Will need mirror clips... REQUEST .2 FOR
          LABOR FOR INSTALL OF CLIP

2        COMPLAINT:  CUSTOMER STATES THAT THE STOPPER AT THE W    1021    FORES
          BOTTOM OF THE SINK IN THE KITCHEN THAT
          IS SUPPOSED TO HOLD WATER DOES NOT HOLD
          ANY WATER-
CAUSE:    the drainer stopper does work insert the
          stopper in sink drain and then turn
          stainless dial to left to lock into
          place for tight seal. NEED .10 FOR
          REPAIR.
CORRECTION: put strainer into place for kitchen sink
          and then turn stainless dial to left to
          lock in
```

Continued on page 2

Work Order : 11707C

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
3      COMPLAINT:  CUSTOMER STATES THAT THE SCREEN DOOR        W    1021    FORES
                DOES NOT GO INTO THE TRACK- IT IS BY THE
                KITCHEN SINK-
                CAUSE:    we need to get ahold mfg about these
                        screen door are not right corners of
                        screen door digging in metal I tried
                        adjusting the wheels seems like they
                        angled the wrong directions does not
                        work with patio frame is there a
                        different option screen door we can try
                        I've come across several like this they
                        don't work I've tried flipping screen
                        door still not right
                CORRECTION: need a different sliding patio screen
                        door REQUEST .5 LABOR FOR SCREEN DOOR
                        REPLACEMENT

```

```

*****
Job # Part No   Description                PARTS                Bill to   Qty    Price    Total
*****
WARR0 822069730 SINK PART: BLACK SINK SPRA W-1021        0      17.16     0.00
1      822091598 CLIP, MIRROR CLEAR PLASTIC W-1021        0       0.07     0.00
3      822053515A SCREEN DOOR FOR PATIO DOOR W-1021        0      53.13     0.00

```

```

*****
Job# Lab Code Description                LABOUR    Mech Bill to   Hrs    Rate    Total
*****
ARR05 Z992      MISC LABOUR CODE (WARR JS    W-1021    0.50   140.00   70.00
SC SC          SERVICE CHARGE          E-17595    0.00   130.00    0.00
1 WARR        MANUFACTURER WARRANTY    JS    W-1021    0.50   140.00   70.00
2 WARR        MANUFACTURER WARRANTY    JS    W-1021    0.50   140.00   70.00
3 WARR        MANUFACTURER WARRANTY    JS    W-1021    0.65   140.00   91.00

```

```

*****
Job # Excode Description                EXTRAS                bill to   Qty    Price    Total
*****
SC SSE          SHOP SUPPLIES - EXTERNAL    E-17595    1.00     0.00     0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W    1021          0.00    301.00     0.00     0.00     0.00    301.00

Totals          0.00    301.00     0.00     0.00     0.00    301.00

```

&k2S

Continued on page 3

Work Order : 11707C

&k0S