

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11710B

Date In:	29 APR 25	Author:	KOTT
Promised Date:	25 DEC 25	Stock No:	11235
:	:	Year:	2025
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	429LFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 5/3
Purchased Date:	25 JAN 25	:	:
Delivery Date:	28 APR 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPU821SP104054	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - RECALL 25V111            W      1021    FORES
          STICKERS ON UNIT NEED TO BE REPLACED
          CAUSE:         stickers was given to customer
          CORRECTION:    customer will install stickers  STICKERS
          WERE SENT NO CHARGE
1        COMPLAINT:  CMR STATES FURNACE IS NOT WORKING. CMR      W      1021    FORES
          STATES THAT HE THOUGHT IT WAS AN LP
          ISSUE BUT CAN GET FLAME TO HIS STOVE.
          CMR STATED THAT HE TRIED TURING THE
          FURNACE ON MULTIPLE TIMES AND IT WOULD
          JUST BLOW AIR FOR A LITTLE BIT AND NOT
          LIGHT. IT WOULD THEN SHUT OFF. NEED DIAG
          *** SUBURBAN AIRXCEL FROM MODELS
          SF-20VHQ TO SF-42VHFQ***
          CAUSE:         pics taken of part used checked voltage
          to furnace was 13.25 the furnace keeps
          trying to light but won't stay on
          checked voltage coming out of control
          board was 10 volts my diagnose is bad
          control module board pics taken of
          model as well
          CORRECTION:    remove and install a new control module
          board to furnace and tested the furnace
          now works  REQUEST 1 HOUR OF LABOR
2        COMPLAINT:  CMR REQUESTS SERVICE CALL TO THEIR UNIT    E      17604    SAWYE
          VISTA ROYALLE SITE# 244
          CORRECTION:    CUSTOMER REQUESTED
```

Continued on page 2

Work Order : 11710B

```
*****
Job # Part No      Description      PARTS      Bill to  Qty      Price      Total
*****
1      755790716500 3G FAN CONTROL MODULE      W-1021      1      130.09      130.09
*****
```

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR JS  W-1021      0.00      140.00      0.00
      1 Z992      MISC LABOUR CODE (WARR JS  W-1021      0.75      140.00      105.00
*****
```

```
*****
Job #  Excode      Description  EXTRAS      bill to  Qty      Price      Total
*****
      2  SSE      SHOP SUPPLIES - EXTERNAL  E-17604      1.00      0.00      0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      130.09      105.00      0.00      0.00      0.00      235.09
      Totals      130.09      105.00      0.00      0.00      0.00      235.09
*****
```

&k2S
&k0S