

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11711B

Date In: 01 OCT 25 Author: MGRAY
Promised Date: 31 DEC 25 Stock No: 11303
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: CEDAR CREEK COTTAGE FW
: WISCONSIN RAPIDS, WI Model: 41FWC
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: NONE Tag#: TV IS IN THE PARTS ROO
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 4X4FCRS38SS234059 :

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT: WARRANTY REPAIR 1 -hydraulic line leaking		W	1021 FORES
	CAUSE: Hydraulic line was loose			
	CORRECTION: Tightened up hydraulic line, no longer leaking	WARRANTY AUTH: .50		
WARR	COMPLAINT: WARRANTY REPAIR 2 -ceiling and living room is delaminating		W	1021 FORES
	CAUSE: Wallpaper delaminating from ceiling			
	CORRECTION: Put up trim to cover delamination	WARRANTY AUTH: 1.4 HOURS		
WARR	COMPLAINT: WARRANTY REPAIR 3 -scuffs and chips throughout the kitchen		W	1021 FORES
	CAUSE: 1016 DAMAGED			
	CORRECTION: Use putty and paint marker to fill in the chips	WARR AUTH: .40		
WARR	COMPLAINT: WARRANTY REPAIR 4 -entry door is leaving a scuff mark on the top of the steps		W	1021 FORES
	CAUSE: Door out of adjustment			
	CORRECTION: Readjusted door now works properly	WARR AUTH: .30 HOURS		
WARR	COMPLAINT: WARRANTY REPAIR 5 -closet by entry door needs to be readjusted		W	1021 FORES
	CAUSE: Hinges were not adjusted properly			
	CORRECTION: Readjusted hinges door closes fine now	WARR AUTH: .20		
WARR	COMPLAINT: WARRANTY REPAIR 6 -drawer and bathroom vanity does not close properly		W	1021 FORES
	CAUSE: Screws are not putting correctly			

Continued on page 2

Work Order : 11711B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CORRECTION: Put in the screws correctly  WARR AUTH:
.10
WARR    COMPLAINT:  WARRANTY REPAIR 7 -ship on drawer in      W    1021  FORES
        front bedroom on the dresser
CAUSE:   1000 DEFECT FROM MANUFACTURER
CORRECTION: Covered up with paint marker  WARR
AUTH: .10 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 8 -hole in screen on      W    1021  FORES
        door
CAUSE:   Screen had a hole in it
CORRECTION: Replace the screen  WARR AUTH: .30
HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 9 -trim and kitchen      W    1021  FORES
        ceiling is falling down
CAUSE:   1018 POOR FITMENT
CORRECTION: Reattach the trim properly  WARR AUTH:
.10 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 10 -TV and front bedroom W    1021  FORES
        flashes on and off does not work
CAUSE:   TV does not stay on flashes on and off
CORRECTION: INSTALLED NEW TV- NOW TESTS OKAY  WARR
AUTH: .50 HOURS  GET TV FROM STORE IN
THE AMOUNT OF $343.00
WARR    COMPLAINT:  WARRANTY REPAIR 11 -door side rear      W    1021  FORES
        downspout is broken
CAUSE:   1016 DAMAGED
CORRECTION: Replace it with new one  WARR AUTH: .20
HOURS
    
```

```

*****
Job # Part No   Description           PARTS   Bill to   Qty   Price   Total
*****
WARR0 51700048    MESH WINDOW SCREEN 48" - W-1021      3     1.17     3.51
WARR1 028985941743 LONG RAIN GUTTER SPOUTS, W-1021      1     6.67     6.67
    
```

```

*****
Job# Lab Code  Description           LABOUR   Mech Bill to   Hrs   Rate   Total
*****
ARR01 Z992     MISC LABOUR CODE (WARR JL  W-1021   0.50  140.00  70.00
ARR02 Z992     MISC LABOUR CODE (WARR JL  W-1021   0.22  140.00  30.80
ARR02 Z992     MISC LABOUR CODE (WARR JL  W-1021   0.18  140.00  25.20
ARR02 Z992     MISC LABOUR CODE (WARR JL  W-1021   0.20  140.00  28.00
ARR02 Z992     MISC LABOUR CODE (WARR JL  W-1021   0.71  140.00  99.40
ARR02 Z992     MISC LABOUR CODE (WARR JL  W-1021   0.09  140.00  12.60
ARR03 Z992     MISC LABOUR CODE (WARR JL  W-1021   0.07  140.00   9.80
ARR03 Z992     MISC LABOUR CODE (WARR JL  W-1021   0.33  140.00  46.20
ARR04 Z992     MISC LABOUR CODE (WARR JL  W-1021   0.30  140.00  42.00
ARR05 Z992     MISC LABOUR CODE (WARR JL  W-1021   0.20  140.00  28.00
ARR06 Z992     MISC LABOUR CODE (WARR JL  W-1021   0.11  140.00  15.40
    
```

Continued on page 3

Work Order : 11711B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR07 Z992      MISC LABOUR CODE (WARR JL  W-1021    0.10   140.00   14.00
ARR08 Z992      MISC LABOUR CODE (WARR JL  W-1021    0.50   140.00   70.00
ARR09 Z992      MISC LABOUR CODE (WARR JL  W-1021    0.15   140.00   21.00
ARR10 Z992      MISC LABOUR CODE (WARR JT  W-1021    0.37   140.00   51.80
ARR10 Z992      MISC LABOUR CODE (WARR JL  W-1021    0.13   140.00   18.20
ARR11 Z992      MISC LABOUR CODE (WARR JL  W-1021    0.20   140.00   28.00
*****
```

```
*****
Job #  Excode    Description  EXTRAS  bill to    Qty    Price    Total
*****
ARR01  SSE        SHOP SUPPLIES - EXTERNAL  W-1021    1.00     0.00     0.00
ARR02  M          MISC BATTEN STRIPS 7/8" X  W-1021    4.00     5.95    23.80
ARR10  M          SMART TV- FROM WAL MART    W-1021    1.00    231.40   231.40
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1021          10.18    610.40     0.00    255.20     0.00    875.78
*****
Totals          10.18    610.40     0.00    255.20     0.00    875.78
*****
```

&k2S
&k0S