

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 11711B

Date In:	01 OCT 25	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11303
:	:	Year:	2025
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	CEDAR CREEK COTTAGE FW
:	: CHICAGO, IL	Model:	41FWC
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB:10/1
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4FCRS38SS234059	:	:

Job #	Description	JOB INFORMATION	Type	Bill To		

WARR	COMPLAINT:	WARRANTY REPAIR 1 -hydraulic line leaking	W	1021	FORES	
	CAUSE:	Hydraulic line was loose				
	CORRECTION:	Tightened up hydraulic line, no longer leaking				
WARR	COMPLAINT:	WARRANTY REPAIR 2 -ceiling and living room is delaminating	W	1021	FORES	
	CAUSE:	Wallpaper delaminating from ceiling				
	CORRECTION:	Put up trim to cover delamination				
WARR	COMPLAINT:	WARRANTY REPAIR 3 -scuffs and chips throughout the kitchen	W	1021	FORES	
	CAUSE:	1016 DAMAGED				
	CORRECTION:	Use putty and paint marker to fill in the chips				
WARR	COMPLAINT:	WARRANTY REPAIR 4 -entry door is leaving a scuff mark on the top of the steps	W	1021	FORES	
	CAUSE:	Door out of adjustment				
	CORRECTION:	Readjusted door now works properly				
WARR	COMPLAINT:	WARRANTY REPAIR 5 -closet by entry door needs to be readjusted	W	1021	FORES	
	CAUSE:	Hinges were not adjusted properly				
	CORRECTION:	Readjusted hinges door closes fine now				
WARR	COMPLAINT:	WARRANTY REPAIR 6 -drawer and bathroom vanity does not close properly	W	1021	FORES	
	CAUSE:	Screws are not putting correctly				
	CORRECTION:	Put in the screws correctly				
WARR	COMPLAINT:	WARRANTY REPAIR 7 -ship on drawer in front bedroom on the dresser	W	1021	FORES	

Continued on page 2

Work Order : 11711B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CAUSE:      1000 DEFECT FROM MANUFACTURER
CORRECTION: Covered up with paint marker
WARR    COMPLAINT:  WARRANTY REPAIR 8 -hole in screen on      W      1021  FORES
           door
CAUSE:      Screen had a hole in it
CORRECTION: Replace the screen
WARR    WARRANTY REPAIR 9 -trim and kitchen ceiling is      W      1021  FORES
           falling down
WARR    WARRANTY REPAIR 10 -TV and front bedroom flashes on W      1021  FORES
           and off does not work
WARR    COMPLAINT:  WARRANTY REPAIR 11 -door side rear      W      1021  FORES
           downspout is broken
CAUSE:      1016 DAMAGED
CORRECTION: Replace it with new one
    
```

```

*****
Job # Part No      Description                PARTS    Bill to    Qty    Price    Total
*****
WARR0 51700048      MESH WINDOW SCREEN 48" - W-1021      3      1.17     3.51
WARR1 028985941743 LONG RAIN GUTTER SPOUTS, W-1021      1      6.67     6.67
    
```

```

*****
Job# Lab Code Description                LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR JL W-1021      0.50   140.00   70.00
ARR02 Z992      MISC LABOUR CODE (WARR JL W-1021      0.00   140.00    0.00
ARR02 Z992      MISC LABOUR CODE (WARR JL W-1021      0.18   140.00   25.20
ARR02 Z992      MISC LABOUR CODE (WARR JL W-1021      0.20   140.00   28.00
ARR02 Z992      MISC LABOUR CODE (WARR JL W-1021      0.12   140.00   16.80
ARR02 Z992      MISC LABOUR CODE (WARR JL W-1021      0.00   140.00    0.00
ARR03 Z992      MISC LABOUR CODE (WARR JL W-1021      0.17   140.00   23.80
ARR03 Z992      MISC LABOUR CODE (WARR JL W-1021      0.33   140.00   46.20
ARR04 Z992      MISC LABOUR CODE (WARR JL W-1021      0.50   140.00   70.00
ARR05 Z992      MISC LABOUR CODE (WARR JL W-1021      0.50   140.00   70.00
ARR06 Z992      MISC LABOUR CODE (WARR JL W-1021      0.50   140.00   70.00
ARR07 Z992      MISC LABOUR CODE (WARR JL W-1021      0.50   140.00   70.00
ARR08 Z992      MISC LABOUR CODE (WARR JL W-1021      0.50   140.00   70.00
ARR09 Z992      MISC LABOUR CODE (WARR JL W-1021      0.50   140.00   70.00
ARR10 Z992      MISC LABOUR CODE (WARR JL W-1021      0.00   140.00    0.00
ARR10 Z992      MISC LABOUR CODE (WARR JL W-1021      0.13   140.00   18.20
ARR11 Z992      MISC LABOUR CODE (WARR JL W-1021      0.50   140.00   70.00
    
```

```

*****
Job # Excode      Description                EXTRAS    bill to    Qty    Price    Total
*****
ARR01 SSE          SHOP SUPPLIES - EXTERNAL    W-1021    1.00     0.00     0.00
ARR02 M           MISC BATTEN STRIPS 7/8" X  W-1021    4.00     5.95    23.80
    
```

Continued on page 3

Work Order : 11711B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	10.18	718.20	0.00	23.80	0.00	752.18
	Totals	10.18	718.20	0.00	23.80	0.00	752.18

&k2S
&k0S