



Warranty Claim Form

Date: 3/6/2025

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573FM4123PBB00142

Momentum 351MS

Retail Purchase Date: null

Work Started: 2/25/2025

Work Completed: 2/25/2025

Claim Status: Paid

Dealer Work Order #: 11714

Unit Offline Date: 11/7/2022

Claim #: 877909

Labor: \$172.50

Parts: \$0.00

Shipping: \$0.00

Total: \$172.50

Notes: AB 2/28 *Please hold all parts for a minimum of 30 days after claim is paid* This unit has open recalls and must be repaired according to Federal Law before customer takes delivery. 910039 - Curt Axle U-Bolt Torque 23V-490/2023-395 910039

Dealer Information

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenewayrv.com
Approved Labor Rate: \$115.00

Customer Information

Operation Line # 1

Flat Rate Code: 610004 Vinyl Board - Repair Panel

Fault Code: Damaged/Maintenance

Problem: One touch monitor is disconnected/falling off the wall. *I am unsure on labor code.

Hours: 1.5

Cause: Due to weak paneling, the screws were not holding, causing the monitor to fall off the wall/sag.

Amount: 172.50

Remedy: Tried two different kinds of rivets, did not work. The asdel paneling is very weak. Had to use large lag screws and gorilla glue.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: