



Warranty Claim Form

Date: 6/27/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FM4123PBB00142
Momentum 351MS
Retail Purchase Date: 5/9/2025
Work Started: 5/14/2025
Work Completed: 5/14/2025

Claim Status: Paid
Dealer Work Order #: 11726B
Unit Offline Date: 11/7/2022

Claim #: 905931
Labor: \$98.00
Parts: \$0.00
Shipping: \$0.00
Total: \$98.00

Notes: TG 910039 axle tag photo's required

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

DAVE STEENBOCK
E8691 STEENBOCK RD
CLINTONVILLE, Wisconsin 54929
United States
7152500105

Operation Line # 1

Flat Rate Code: 910039 Recalls/Field Campaign - Curt Axle U-Bolt *Fault Code:* Recall
Torque 23V-490/2023-395 910039

Problem: Recall 23v-490

Hours: .5

Cause: Recall 23v-490

Amount: 70.00

Remedy: Torque all U-bolts to correct torque. Torqued the bolts to 90 ft pounds.

Sublet Repairs: \$0.00

Manufacturer #: 1

Model #: 1

Serial #: 1

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
961751 LIPPERT LABOR ONLY	LIPPERT LABOR ONLY		1	1	0.00

Operation Line # 2

Flat Rate Code: 580012 Slider/Crank Out Windows - Repair *Fault Code:* Improper Installation/Build
Window

Problem: Window will not stay up properly, one side hangs lower than other.

Hours: .2

Cause: Window was installed this way from the manufacturer.

Amount: 28.00

Remedy: There is nothing I can do to repaid this. Window opens and closes, stays open when lifted and is sealed when closed. It just looks a bit uneven when closed, but not real back. It's the window to the left of the main bedrooms bed. Could not be adjusted, I tried it in all positions and window seems to do its purpose.

Manufacturer #:

Model #:

Serial #: