

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 11729C

|                 |                       |                 |                       |
|-----------------|-----------------------|-----------------|-----------------------|
| Date In:        | 26 FEB 25             | Author:         | KOTT                  |
| Promised Date:  | 25 FEB 25             | Stock No:       | 11297                 |
| :               | :                     | Year:           | 2025                  |
| Customer Name:  | 16652 - BALE, RICHARD | Manufacturer:   | FOREST RIVER          |
| Address:        | 5805 OAK LANE         | Brand:          | FLAGSTAFF E-PRO       |
| :               | EDINA, MN             | Model:          | E19FD                 |
| Postal/Zip:     | 55436                 | Miles/Hrs:      | 0                     |
| Phone#(res):    | 612-325-1811          | Exterior Color: | :                     |
| Phone#(bus):    | :                     | Unit Type:      | TT-TRAVEL TRAILER     |
| Cell Phone:     | :                     | License#:       | :                     |
| Email:          | rbale@larsonking.com  | Tag#:           | PU@ST-2/25@11 DB 2/28 |
| Purchased Date: | 05 NOV 24             | :               | :                     |
| Delivery Date:  | 25 FEB 25             | :               | :                     |
| InService Date: | :                     | :               | :                     |
| Serial#:        | 5ZT2FSHC1S3037205     | :               | :                     |

\*\*\*\*\*

| Job # | Description | JOB INFORMATION                          | Type | Bill To    |
|-------|-------------|------------------------------------------|------|------------|
| 2     | COMPLAINT:  | Furnace will turn on and then turn off   | W    | 1021 FORES |
|       | CAUSE:      | will not stay running                    |      |            |
|       |             | Upon diagnosis by eliminating thermostat |      |            |
|       |             | found furnace would stay running, found  |      |            |
|       |             | broken connectors on thermostat and      |      |            |
|       |             | siliconed wires, removed silicone found  |      |            |
|       |             | blue wire (thermostat wire) pulls out    |      |            |
|       |             | not making a good connection because of  |      |            |
|       |             | broken clip.                             |      |            |
|       | CORRECTION: | Replaced thermostat with new thermostat  |      |            |
|       |             | furnace operates as it should.           |      |            |
|       |             | REQUESTING .50 HOURS                     |      |            |

\*\*\*\*\*

| Job # | Part No      | Description                     | PARTS | Bill to | Qty | Price | Total |
|-------|--------------|---------------------------------|-------|---------|-----|-------|-------|
| 2     | 755790005147 | T-STAT WALL DIGITAL HEAT W-1021 |       |         | 1   | 90.82 | 90.82 |

\*\*\*\*\*

| Job# | Lab Code | Description           | LABOUR | Mech | Bill to | Hrs  | Rate   | Total |
|------|----------|-----------------------|--------|------|---------|------|--------|-------|
| 2    | WARR     | MANUFACTURER WARRANTY | CF     |      | W-1021  | 0.50 | 115.00 | 57.50 |

\*\*\*\*\*

BILLINGS SUMMARY

| Type | Bill Id | Parts | Labour | Sublet | Extras | Tax  | Total  |
|------|---------|-------|--------|--------|--------|------|--------|
| W    | 1021    | 90.82 | 57.50  | 0.00   | 0.00   | 0.00 | 148.32 |

\*\*\*\*\*

Continued on page 2

Work Order : 11729C

\*\*\*\*\*

## BILLINGS SUMMARY

| Type Bill Id | Parts | Labour | Sublet | Extras | Tax  | Total  |
|--------------|-------|--------|--------|--------|------|--------|
| *****        |       |        |        |        |      |        |
| Totals       | 90.82 | 57.50  | 0.00   | 0.00   | 0.00 | 148.32 |

&k2S  
&k0S