

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11735

Date In:	11 FEB 25	Author:	KOTT
Promised Date:	31 MAY 25	Stock No:	
:		Year:	2022
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	REREFLECTION
:	MIDDLEBURY, IN	Model:	337RLS
Postal/Zip:	46540	Miles/Hrs:	
Phone#(res):	888-825-2820	Exterior Color:	
Phone#(bus):		Unit Type:	FW-FIFTH WHEEL
Cell Phone:		License#:	
Email:	NONE	Tag#:	ORDERING WALLS- 4/7
Purchased Date:		:	
Delivery Date:		:	
InService Date:		:	
Serial#:	573FR3725N9917696	:	

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
1       COMPLAINT:  CUSTOMER HAS CLAIM WITH GRAND DESIGN-      W      1020      GRAND
          CUSTOMER STATES THAT THE ODS SLIDE OUT
          THE MAIN SLIDE OUT- THE VERTICAL
          ALUMINUM BEAMS ARE COMING LOOSE- THE DS
          SLIDE OUT IS ALSO DOING THE SAME THING
          BUT NOT AS BAD- NEEDS TO BE INSPECTED
          FOR POSSIBLE FRAME ISSUES- YOU CAN ONLY
          SEE IF FROM THE INSIDE- CMR STATES THAT
          THE FASCIA PEICE IS MISSING AND YOU CAN
          SEE THE BEAM WERE IT IS ATTACHED AT THE
          TOP BUT NOT AT THE BOTTOM- ***SEE
          PICTURES*****
          CAUSE:      Interior facia on ds and ods are
          seperating from the slide wall on the
          rear of both slides. Recommend new
          replacement slide walls. Will have to
          hyper extend both slides to do the
          repair.requesting 16 hours per slide
          wall. Would have to remove window on ds
          slide. And detach entertainment cabinet
          on ods slide.
          CORRECTION: Removed damaged end wall on the ods rear
          slide. Install new wall then seal back
          up. REQUESTING 32 HOURS  APPROVED 24
          HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 1 - QUICK DISCONNECT      W      1020      GRAND
          RECALL 961563
          CAUSE:      Quick disconnect recall
```

Continued on page 2

Work Order : 11735

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: Installed 2 new quick disconnects.
            Perform drop pressure test. Tested good
            for no leaks.
WARR    COMPLAINT: WARRANTY REPAIR 2- THE SLIDE TIMING IS W    1020    GRAND
            OFF AND WILL NEED TO BE ADJUSTED ON BOTH
            REAR SLIDES
            CAUSE:   Ds slide out needs to be adjusted for
            stop time when going out to prevent
            facia on the inside from being torn off.
            CORRECTION: Adjusted the main drive ram for stopping
            distance. Tested good. REQUESTING 3
            HOURS (1.5 HOURS PER SLIDE) APPROVED

```

```

*****
Job # Part No   Description                PARTS                Bill to   Qty    Price    Total
*****
1      8220570088 TRIM SLIDE OUT SKI RIGHT B W-1020        1        7.84      7.84
WARR0 822020061  QUICK DISCONNECT X 1/4 BRA W-1020        2       24.01     48.02
WARR0 82203706  ENDWALL RIGHT S/O COMPLETE W-1020        0     443.05      0.00
WARR0 82205119  ENDWALL LEFT S/O COMPLETE W-1020        0     382.54      0.00

```

```

*****
Job# Lab Code Description                LABOUR    Mech Bill to    Hrs    Rate    Total
*****
1 WARR    MANUFACTURER WARRANTY TD W-1020    15.00  115.00  1,725.00
1 WARR    MANUFACTURER WARRANTY TD W-1020     5.00  115.00   575.00
1 WARR    MANUFACTURER WARRANTY TD W-1020     4.00  115.00   460.00
1 WARR    MANUFACTURER WARRANTY TD W-1020     0.00  115.00     0.00
1 WARR    MANUFACTURER WARRANTY TD W-1020     0.00  115.00     0.00
1 WARR    MANUFACTURER WARRANTY TD W-1020     0.00  115.00     0.00
1 WARR    MANUFACTURER WARRANTY TD W-1020     0.00  115.00     0.00
ARR01 Z992 MISC LABOUR CODE (WARR TD W-1020    0.50  115.00    57.50
ARRO2 Z992 MISC LABOUR CODE (WARR TD W-1020     3.00  140.00   420.00

```

```

*****
Job # Sublet Description                SUBLET                bill to    Vendor    Total
*****
ARRO2 BDT                                W-1020    329-BDT INC    0.00

```

```

*****
Job # Excode   Description                EXTRAS                bill to    Qty    Price    Total
*****
1 SC          SERVICE CALL W-1020        1.00     3.75     3.75
1 SSE        SHOP SUPPLIES - EXTERNAL W-1020     1.00     0.00     0.00
ARRO2 FRT    FREIGHT FOR SO WALL B13706 W-1020     1.00   195.84   195.84
ARRO2 FRT    FREIGHT FOR END WALL B1511 W-1020     1.00   162.40   162.40
ARRO2 M      MISCELLANEOUS BATTEN TRIM W-1020     1.00    29.97    29.97

```

Continued on page 3

Work Order : 11735

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1020	55.86	3237.50	0.00	391.96	0.00	3,685.32
	Totals	55.86	3237.50	0.00	391.96	0.00	3,685.32

&k2S
&k0S