



Warranty Claim Form

Date: 6/5/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3725N9917696
Reflection 337RLS
Retail Purchase Date: 12/15/2021
Work Started: 5/20/2025
Work Completed: 5/20/2025

Claim Status: Paid
Dealer Work Order #: 11735
Unit Offline Date: 10/26/2021
Claim #: 900028
Labor: \$420.00
Parts: \$0.00
Shipping: \$0.00
Total: \$420.00

Notes: overed as goodwill This unit has open recalls and must be repaired according to Federal Law before customer takes delivery. 910045 - Quick Disconnect (supersedes 910029) JH 4/1 : Factory Warranty Expired 12/15/2022. Denied

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Niki Myers
6612 VISTA VLY
WINDSOR, Wisconsin 53598-9120
United States
6152071026

Operation Line # 1

Flat Rate Code: 640007 Slide Out Ramp/Pan/Rollers - Adjust (Shim) *Fault Code:* Damaged/Maintenance
Slide Rollers*

Problem: The slide timing is off and will need to be adjusted on both rear slides.

Hours: 3

Cause: The timing for the slide is off causing the bell of the slides to be compressed against the frame.

Amount: 420.00

Remedy: Once the sublet company welds the frame where the bell sits, we will need to readjust the bells on both rear slides. (1.5 hour per slide)

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: