

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 11737

Date In: 12 FEB 25 Author: KOTT
 Promised Date: 04 JUL 25 Stock No: 11266
 : Year: 2025
 Customer Name: 17602 - KISER, NICHOLA Manufacturer: FOREST RIVER
 Address: 134 S DEWEY AVENUE Brand: PUMA CAMPING EDITION
 : JEFFERSON, WI Model: 305BHCE
 Postal/Zip: 53549 Miles/Hrs: 0
 Phone#(res): 9203926900 Exterior Color:
 Phone#(bus): Unit Type: TT-TRAVEL TRAILER
 Cell Phone: License#:
 Email: nick.kiser515@gmail.co Tag#: PD@ST DB2/12- CMR CALL
 Purchased Date: 25 JAN 25 :
 Delivery Date: 04 JUL 25 :
 InService Date: :
 Serial#: 5ZT2PUWB9S4023338 :

```
*****
Job # Description JOB INFORMATION Type Bill To
*****
1 TRADE INFO: 2012 W.W. DLX 372REDS I DO DEALE
SCP COMPLAINT: SOLD COMPLETE PREP I PDI PRE-D
CAUSE: Complete prep
CORRECTION: Competed complete prep
CEN COMPLAINT: CLEAN EXTERIOR- NEW I PDI PRE-D
CAUSE: Camper needs to be de salted and washed
CORRECTION: De salted camper and then washed the
camper
CIN CLEAN INTERIOR- NEW I PDI PRE-D
WARR COMPLAINT: WARRANTY REPAIR 1 - OVER SPRAY OF W 1021 FORES
ADHISIVE UNDER OUTLET BY DINETE IN SLIDE
OUT
CAUSE: Some kind of adhesive below dinette
outlet
CORRECTION: Quick hit of quik-solve and a rag
cleaned it up
WARR COMPLAINT: WARRANTY REPAIR 2 - THERE IS NO CAPACITY W 1021 FORES
STICKER FOR THE MURPHY BED
CAUSE: Sticker missing, needs to be ordered,
see title for Line.
CORRECTION: ...
WARR COMPLAINT: WARRANTY REPAIR 3 - SOME OF THE SEAMS ON W 1021 FORES
THE CORNERS OF THE BUNK ROOM ARE COMING
CAUSE: Manufacturer defects
CORRECTION: Played with the seams using a puddy
stick, they wouldn't lay flat, did them
all with white nova-flex.
WARR COMPLAINT: WARRANTY REPAIR 5 - NOTICE STICKER W 1021 FORES
```

Continued on page 2

Work Order : 11737

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                TORE/BROKE AND NEEDS TO BE REPLACED
                                CAUSE: R&R notice sticker
                                CORRECTION: Completed.
WARR    COMPLAINT: WARRANTY REPAIR 6 - SEAM TAPE IS COMING W    1021    FORES
                                UP IN THE MASTER BEDROOM
                                CAUSE: Unknown, examined all seams in bedroom.
                                CORRECTION: NPF
3       1072 14TH CT ARKDALE, WI                                I    DO    DEALE
ZAS     ZONE A- STANDARD SET                                I    DO    DEALE
WARR    COMPLAINT: Transferred to GRV*11737C on 27 FEB 25 W    1021    FORES
                                Estimate amount was 0.00 WARRANTY REPAIR
                                7 - Floor Vent Broken
                                CAUSE: Cracked, overtightned screw, light Grey
                                color floor vend needs replacement.
                                Order per warranty. 2" x10"
                                CORRECTION: ...
WARR    COMPLAINT: Transferred to GRV*11737C on 27 FEB 25 W    1021    FORES
                                Estimate amount was 0.00 WARRANTY REPAIR
                                8 - decal, front slide replacement
                                CAUSE: Black decal on front ODS slide is
                                bubbling the entire length. Will require
                                replacement. Decal is roughly 123" x 4"
                                CORRECTION: ...

```

```

*****
Job # Part No   Description                PARTS   Bill to   Qty   Price   Total
*****
SCP   840821034507 12V 24 MDP BATTERY           I-PDI   0       85.20   0.00
CIN   019079236326 TOILET TISSUE, SGL. 2 PL I-PDI   0       1.02   0.00
CIN   014717396042 HTS STANDARD 10' SEWER H I-PDI   0       7.46   0.00
CIN   019079900142 PARK ADAPTER BULK 30-15 I-PDI   0       4.34   0.00

```

```

*****
Job# Lab Code Description                LABOUR   Mech Bill to   Hrs   Rate   Total
*****
SCP  RV1F-3   SOLD COMPLETE PREP           RW   I-PDI   1.01   70.00  70.70
CEN  CE      CLEAN EXTERIOR                RW   I-PDI   1.05   70.00  73.50
CIN  CI      CLEAN INTERIOR                I-PDI 0.00   70.00  0.00
ARR01 Z992   MISC LABOUR CODE (WARR RW   W-1021 0.50  115.00  57.50
ARR02 Z992   MISC LABOUR CODE (WARR RW   W-1021 0.50  115.00  57.50
ARR03 Z992   MISC LABOUR CODE (WARR RW   W-1021 0.50  115.00  57.50
ARR05 Z992   MISC LABOUR CODE (WARR RW   W-1021 0.50  115.00  57.50
ARR06 Z992   MISC LABOUR CODE (WARR RW   W-1021 0.00  115.00  0.00
ZAS  Z991   MISC CODE (INTERNAL)         I-DO  0.00  140.00  0.00
ARR06 Z992   MISC LABOUR CODE (WARR RW   W-1021 0.50  115.00  57.50
ARR07 Z992   MISC LABOUR CODE (WARR RW   W-1021 0.00  115.00  0.00
ARR08 Z992   MISC LABOUR CODE (WARR RW   W-1021 0.00  115.00  0.00
ARR07 Z992   MISC LABOUR CODE (WARR RW   W-1021 0.00  115.00  0.00
ARR02 Z992   MISC LABOUR CODE (WARR RW   W-1021 0.00  115.00  0.00

```

Continued on page 3

Work Order : 11737

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR08 Z992      MISC LABOUR CODE (WARR RW  W-1021    0.00   115.00    0.00
  SCP RV1F-3    SOLD COMPLETE PREP      RW  I-PDI     0.24    70.00   16.80
  SCP RV1F-3    SOLD COMPLETE PREP      RW  I-PDI     1.44    70.00  100.80
  SCP RV1F-3    SOLD COMPLETE PREP      RW  I-PDI     1.67    70.00  116.90
  SCP RV1F-3    SOLD COMPLETE PREP      RW  I-PDI     0.14    70.00    9.80
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to    Qty    Price    Total
*****
  SCP  LP      PROPANE                I-PDI     0.00    0.00    0.00
ARR07  SSE      SHOP SUPPLIES - EXTERNAL  W-1021    0.00    0.00    0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I   PDI            0.00    388.50    0.00     0.00     0.00    388.50
W   1021           0.00    287.50    0.00     0.00     0.00    287.50

      Totals      0.00    676.00    0.00     0.00     0.00    676.00
*****
```

&k2S
&k0S