

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11737

Date In: 12 FEB 25 Author: RBOGGS
Promised Date: 04 JUL 25 Stock No: 11266
: Year: 2025
Customer Name: 17602 - KISER, NICK Manufacturer: FOREST RIVER
Address: 134 S DEWEY AVENUE Brand: PUMA CAMPING EDITION
: JEFFERSON, WI Model: 305BHCE
Postal/Zip: 53549 Miles/Hrs: 0
Phone#(res): 9203926900 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: nick.kiser515@gmail.co Tag#: PD@ST
Purchased Date: 25 JAN 25 :
Delivery Date: 04 JUL 25 :
InService Date: :
Serial#: 5ZT2PUWB9S4023338 :

Job #	Description	JOB INFORMATION	Type	Bill To
1	TOW: BC: YN TP: YN HITCH:		I	DO DEALE
PDIT	SOLD FINISH PREP TRAVEL TRAILER		I	PDI PRE-D
SCP	SOLD COMPLETE PREP		I	PDI PRE-D
CEN	CLEAN EXTERIOR- NEW		I	PDI PRE-D
CIN	CLEAN INTERIOR- NEW		I	PDI PRE-D
2	DE-SALT		I	PDI PRE-D
WARR	COMPLAINT: WARRANTY REPAIR 1 - OVER SPRAY OF ADHISIVE UNDER OUTLET BY DINETE IN SLIDE OUT		W	1021 FORES
	CAUSE: NEED TO CLEAN WITH HOT WATER AND DAWN DISH SOAP			
	CORRECTION: REQUESTING .50 LABOR			
WARR	COMPLAINT: WARRANTY REPAIR 2 - THERE IS NO CAPACITY W STICKER FOR THE MURPHY BED		W	1021 FORES
	CAUSE: NEED 250LB CAPACITY STICKER FOR MURPHY BED			
	CORRECTION: REQUESTING STICKER			
WARR	COMPLAINT: WARRANTY REPAIR 3 - SOME OF THE SEAMS ON W THE CORNERS OF THE BUNK ROOM ARE COMING		W	1021 FORES
	CAUSE: WE WILL TRY TO LAY THE CORNERS DOWN AS BEST WE CAN OTHERWISE WE WILL HAVE TO TRIM THEM A LITTLE AND THEN PUT SILICONE OVER THE CORNERS			
	CORRECTION: REQUESTING 1 HOUR LABOR			
WARR	COMPLAINT: WARRANTY REPAIR 4 - THERE IS A GAP BETWEEN THE BATEN STRIPS AND THE CORNER OF THE WALL IN BUNK ROOM		W	1021 FORES
	CAUSE: NEED TO FILL IN GAP WITH SILICONE			

Continued on page 2

Work Order : 11737

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: REQUESTING .50 LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 5 - NOTICE STICKER          W      1021    FORES
        TORE/BROKE AND NEEDS TO BE REPLACED
        CAUSE:          R&R TIRE NOTICE STICKER
CORRECTION: REQUESTING .50 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 6 - SEAM TAPE IS COMING W      1021    FORES
        UP IN THE MASTER BEDROOM
        CAUSE:          WE WILL TRY TO LAY THE SEAM TAPE BACK
        DOWN AS IT IS STILL STICKY BUT IF THAT
        DOESN'T STAY THEN WE WILL HAVE TO
        REPLACE THE SEAM TAPE
CORRECTION: REQUESTING .50 HOURS
*****
```

```
*****
Job # Part No   Description                PARTS    Bill to   Qty    Price    Total
*****
PDITT 840821034507 12V 24 MDP BATTERY          I-PDI    0      85.20    0.00
SCP   840821034507 12V 24 MDP BATTERY          I-PDI    0      85.20    0.00
CIN   019079236326 TOILET TISSUE, SGL. 2 PL I-PDI    0      1.02     0.00
CIN   014717396042 HTS STANDARD 10' SEWER H I-PDI    0      7.46     0.00
CIN   019079900142 PARK ADAPTER BULK 30-15 I-PDI    0      4.34     0.00
*****
```

```
*****
Job# Lab Code Description                LABOUR    Mech Bill to   Hrs    Rate    Total
*****
PDITT RV1F-3B  SOLD FINISH PREP TRAVE          I-PDI    0.00    70.00    0.00
SCP   RV1F-3    SOLD COMPLETE PREP              I-PDI    0.00    70.00    0.00
CEN   CE      CLEAN EXTERIOR                  I-PDI    0.00    70.00    0.00
CIN   CI      CLEAN INTERIOR                  I-PDI    0.00    70.00    0.00
      2 Z991    MISC CODE (NTERNAL)            CF      I-PDI    0.51    70.00    35.70
      2 Z991    MISC CODE (NTERNAL)            CF      I-PDI    0.49    70.00    34.30
ARR01 Z992    MISC LABOUR CODE (WARR          W-1021    0.00    115.00    0.00
ARR02 Z992    MISC LABOUR CODE (WARR          W-1021    0.00    115.00    0.00
ARR03 Z992    MISC LABOUR CODE (WARR          W-1021    0.00    115.00    0.00
ARR04 Z992    MISC LABOUR CODE (WARR          W-1021    0.00    115.00    0.00
ARR05 Z992    MISC LABOUR CODE (WARR          W-1021    0.00    115.00    0.00
ARR06 Z992    MISC LABOUR CODE (WARR          W-1021    0.00    115.00    0.00
*****
```

```
*****
Job # Excode   Description                EXTRAS    bill to   Qty    Price    Total
*****
PDITT LP      PROPANE                    I-PDI    0.00    0.00    0.00
SCP   LP      PROPANE                    I-PDI    0.00    0.00    0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id   Parts    Labour    Sublet    Extras    Tax    Total
*****
I    PDI      0.00     70.00     0.00     0.00     0.00     70.00
*****
```

Continued on page 3

Work Order : 11737

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
Totals	0.00	70.00	0.00	0.00	0.00	70.00

&k2S
&k0S