

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 2199227
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2PUWB9S4023338
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 425 / 425
 ITEM # PUT305BHCE-1
 DEALER RO # 11737
 CLAIM START DATE 02/12/2025
 CLAIM END DATE 03/26/2025

Labor rate: \$115.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-102-24-00-001094 Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/
 Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-02-12 13:40:09 :: Complaint: Overspray of adhesive under outlet by dinette in slide out. Cause: From factory Correction: Need to clean with hot water and dawn dish soap.

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$57.50
Serial#	Appr Hrs	0.30	Appr Labor Amt \$34.50

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 30-92-01-00-001112 Information Sticker or Decal - Interior/Interior Miscellaneous/Replace/No Tread
 Code

Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-02-12 13:41:50 :: Complaint: There is no capacity sticker for the murphy bed. Cause: From factory Correction: Need 250lb capacity sticker for murphy bed.

Model#	Dlr Sub Hrs	0.05	Sub Labor Amt \$5.75
Serial#	Appr Hrs	0.05	Appr Labor Amt \$5.75

Notes

Labor

Line# 3 **Operation Code** **Operational Description**
 30-102-12-00-001096 Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/
 Resecure or Tighten/No Tread Code

Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-02-12 13:44:10 :: Complaint: Some of the seams on the corners of the bunk room are coming up. Cause: Trim is coming loose at the corners. Correction: We will try to lay the corners down as best we can otherwise, we will have to trim them a little and then put silicone over the corners.

Model#	Dlr Sub Hrs	1.00	Sub Labor Amt \$115.00
Serial#	Appr Hrs	0.30	Appr Labor Amt \$34.50

Notes
 repair

Labor

Line# 4 **Operation Code** **Operational Description**
 30-102-24-00-004562 Gimp/Vinyl Trim - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread
 Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-02-12 13:45:30 :: Complaint: There is a gap between the batten strips and the corner of the wall in the bunk room. Cause: Gap between batten strips and the corner from factory. Correction: Need to fill the gap in with silicone.

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$57.50
 Serial# Appr Hrs 0.05 Appr Labor Amt \$5.75

Notes
 seal gap

Labor

Line# 5 Operation Code 30-92-01-00-001112 Operational Description Information Sticker or Decal - Interior/Interior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-02-12 13:46:29 :: Complaint: Notice sticker tore/broke and needs to be replaced. Cause: Notice sticker is damaged. Correction: R&R tire notice sticker.

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$57.50
 Serial# Appr Hrs 0.05 Appr Labor Amt \$5.75

Notes

Labor

Line# 6 Operation Code 30-102-01-00-001097 Operational Description Seam Tape, per 8 ft. Strip - Interior/Panels, Ceilings, & Interior Moldings/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-02-12 13:47:50 :: Complaint: Seam tape is coming up in the master bedroom. Cause: Seam tape is coming up in bedroom. Correction: We will try to lay the seam tape back down as it is still sticky, but if that doesn't stay then we will have to replace the seam tape.

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$57.50
 Serial# Appr Hrs 0.10 Appr Labor Amt \$11.50

Notes

Submitted	Labor Amt	\$350.75	Approved	Labor Amt	\$97.75
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$350.75		Total	\$97.75

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.